



19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SMK8896S	MODEL : XV 2.0I-S EYESIGHT AWD CVT
REF NO:INS/IC/CHI/0229/2021	YEAR: 27-APR-2019
ENGINE NO: FB20CE25197	CHASSIS NO: JF1GT7KL5KG063136
DOA: 10/11/2021	TOA: 1905HRS
TYPE OF CLAIM: 3RD PARTY	INS COMPANY: SOMPO

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE REAR BUMPER, BEAM & PANEL	\$1000.00
2.	RESPRAY REAR BUMPER, BEAM & PANEL	\$1000.00
3.	FAULT DIAGNOSTIC	\$235.00
4.	TO CONDUCT REAR LIGHTING TEST	\$28.00
5.	TO ONDUCT REAR PROTECTANT COATING	\$250.00
6.	TO CONDUCT REAR ANTI RUST COATING	\$250.00
7.	TO SUPPLY & INSTALL REVERSE SENSOR – 2 EYES	\$300.00
8.	SUNDRIES	\$100.00
9.		
10.		
	Total Labour	\$3163.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	
HP / EMAIL:	/
BEFORE PAINT:	
DAYS GIVEN:	

PO #:

Account #:

Date: 2021-11-11

Dealer Information	Customer Information
Name:	Name: SMK8896S
Address:	Address:
Phone:	Phone:
Fax:	Email:
Contact: Simon Kam	Contact:

Vehicle Information
VIN: JF1GT7KL5KG063136 Vehicle: 2019 > XV VIN:JF1,2 (G24)

Part No.	Description	Qty	Unit Price	Price
57704FL250	BUMPER-FACE,REAR	1	414.00	414.00
57707FL400	BRACKET-REAR BUMPER SIDE,RIGHT	1	12.10	12.10
57707FL510	BRACKET-REAR BUMPER,LOWER	1	12.60	12.60
57711FL0419P	BACK BEAM COMPLETE-REAR	1	202.90	202.90
57731FL570NN	COVER-REAR BUMPER	1	6.48	6.48
57731FL500	COVER-BUMPER,SIDE REAR RIGHT	1	20.90	20.90
57731FL510	COVER-BUMPER,SIDE REAR LEFT	1	20.90	20.90

Labor Hours:	Labor Rate:	Labor:	
Currency: SIN \$	Shipping Method:	Shipping:	
		Subtotal:	689.88
	Tax Rate: 7.00	Tax:	48.29
		Total:	738.17

Dealer Message:
