



19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SMN5064E	MODEL : XV 2.0I-S EYESIGHT AWD CVT
REF NO:	YEAR: 15-AUG-2019
ENGINE NO: FB20CF34431	CHASSIS NO: JF1GT7KL5KG070425
DOA: 17/11/2021	TOA: 16:34 HRS
TYPE OF CLAIM: 3RD PARTY	INS COMPANY: CHINA TAIPING INSURANCE

S/N	NATURE OF JOB	AMOUNT
1.	REMOVE & REPLACE REAR BUMPER,BUMPER BEAM,BRACKET	\$580.00
2.	RESPRAY REAR BUMPER ASSY,BUMPER BEAM	\$960.00
3.		\$
4.		\$
5.		\$
6.		\$
7.		\$
8.		\$
9.		
10.		
	Total Labour	\$1540.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	
HP / EMAIL:	/
BEFORE PAINT:	
DAYS GIVEN:	

Estimate

Date 11 / 18 / 2021

001 / 001

Name	SMN5064E	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	G24
		Body Model	GT7CKVL
		Vin-Code	JF1GT7KL5KG070425

Part Number	Part Code Name	Part Code	Q'ty	Price
57702FL220	BUMPER-FACE, REAR	FIG-591 57704A	1	403. 20
57707FL400	BRACKET-REAR BUMPER SIDE, RIGHT	FIG-591 57707H	1	12. 10
57707FL410	BRACKET-REAR BUMPER SIDE, LEFT	FIG-591 57707I	1	12. 10
57711FL0419P	BACK BEAM COMPLETE-REAR	FIG-591 57711D	1	202. 90
		Page-Total		630. 30
		Sub-Total		630. 30
		Total		630. 30
		Tax		0. 00
		Grand Total		630. 30

Memo

Grand Total
630. 30

--

Tel
