

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Survey & Repair
22.11 @ 11 am ✓
Additional
Low for late
survey

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 59597
Date Estimated : 23/09/2021
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Selliah Pandiaraja
21 Lorong 3 Toa Payoh
#04-06

Singapore 319581

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKF1551H	WBA1A12020E951157	30/04/2012	1161A/5	70210

DESCRIPTION

To replace rear bumper, rear left door including to knock out rear left fender and dented area caused by the accident

3400 ~~4,250.00~~

To respray rear bumper, left front door, left rear door and left rear fender

3508 ~~3,693.00~~

To carry out body cavity preservation.
(Per panel).

112 ~~118.00~~

To conduct check on all doors and bootlid central locking system for proper function.

168 ~~177.00~~

To check electrical wiring system and lighting at the rear section for proper function.

168 ~~177.00~~

Sundries.

? 150.00

Total Labour 1: 8,565.00

DESCRIPTION

RR LH DOOR ~~54~~ ?
RR BUMPER LH SIDE GUIDE ?
REAR BUMPER PRIMED (LINES) repair
SET MOUNTS PDC SENSOR REAR X
FRT LH DOOR CHANNEL SEALING seal
(DG/SL) ADHESIVE SET K6 X

QTY	PRIC	VALUE
1	1,088.15	1,088.15
1	127.90	127.90
1	971.50	971.50
1	59.20	59.20
1	72.95	72.95
1	53.05	53.05

Total Parts : 2,372.75

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 59597
Date Estimated : 23/09/2021
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKF1551H	WBA1A12020E951157	30/04/2012	116iA/5	70210

Claims 3rd Party / Uninsured losses / Direct Settlement

Reg No. _____ Claim No. _____

Date 23/11/2020 Excess S\$ _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Time _____

Authorised Date _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 7 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	8,565.00
Parts	:	2,372.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	765.64
Grand Total	:	11,703.39

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **