

YP5022Z Isuzu Reward

No. [REDACTED]			
1	1	Front bumper assy	648 \$ 1,290.00 <i>car</i>
2	1	Front right bumper bracket	\$ 160.00 <i>bb</i>
3	1	Front bumper reinforcement	\$ 375.00 <i>Run.</i>
4	1	Front bumper right fog lamp cover	\$ 192.00 <i>dis</i>
5	1	Front panel assy	828.70 \$ 1,285.00 <i>dp</i>
6	1	Front inner panel assy	\$ 1,910.00 <i>Rp</i>
7	1	Front panel 'isuzu' emblem	\$ 128.00 <i>net</i>
8	1	Front right corner panel	\$ 271.00 <i>mis</i>
9	1	Front right inner corner panel	\$ 899.00 <i>X R</i>
10	1	Front grille assy	475.70 \$ 693.00 <i>we</i>
11	1	Front right headlamp	410 \$ 769.00 <i>car</i>
12	1	Front torsion bar	\$ 846.00 <i>x un</i>
13	2	Front torsion bar bushing	\$ 185.00 <i>x un</i>
14	1	Front right door signal lamp	\$ 92.00 <i>ent</i>
15	1	Front right door panel	1187 \$ 1,560.00 <i>be</i>
16	1	Front right door moulding	\$ 187.00 <i>ent</i>
17	1	Front right door outer handle	\$ 124.00 <i>x un</i>
18	2	Front right door hinges	\$ 160.00 <i>bl</i>
19	1	Front right door inner step board	\$ 277.00 <i>de 130</i>
20	1	Front right door inner trim board	\$ 356.00 <i>Run 288</i>
21	1	Front right door outer step garnish	\$ 267.00 <i>mis</i>
22	1	Front right door step reflector	\$ 68.00 <i>x un</i>
23	1	Front right door lock mechanism	\$ 162.00 <i>x un</i>
24	1	Front right door checker linkage	\$ 136.00 <i>bt</i>
25	1	Front right door window regulator	\$ 376.00 <i>x un</i>
26	1	Front right door window motor	\$ 451.00 <i>x un</i>
27	1	Front right door outer moulding	\$ 188.00 <i>x un</i>
28	1	Front right door inner weathership	\$ 128.00 <i>ent</i>
29	1	Front right door outer weathership	\$ 168.00 <i>ent</i>
30	1	Front right side mirror	\$ 653.00 <i>mis 215</i>
31	1	Front right mudflap	\$ 215.00 <i>x un</i>
32	1	Front wiper tank	\$ 108.00 <i>x un</i>
33	1 set	Front wiper blade assy	\$ 140.00 <i>ent</i>
34	1 set	Front wiper spray washer nozzle	\$ 160.00 <i>ent</i>
35	1	Front wiper inner panel	\$ 650.00 <i>Rp</i>
36	1	Front wiper outer panel	\$ 791.00 <i>Rp</i>
37	1	Front dashboard assy	\$ 2,515.00 <i>x g</i>
38	1	Front dashboard glove box	\$ 183.00 <i>x</i>
39	1	Front dashboard centre beam	\$ 377.00 <i>x un</i>
40	1	Front dashboard centre console	\$ 512.00 <i>x</i>
41	1	Front windscreen glass assy	1300 \$ 2,670.00 <i>un</i>
42	1	Front windscreen glass moulding	245 \$ 388.00 <i>un</i>
43	1	Front right antenna assy	160 \$ 280.00 <i>ent</i>

YP5022Z Isuzu Reward

No. [REDACTED]

44	1	Front right "A" pillar	\$	798.00	✓
45	1	Front right "A" pillar inner garnish	\$	185.00	✓
46	1	Front steering column assy	\$	3,879.00	✓
47	1	Front brake booster	\$	1,255.00	✓
48	1	Front clutch master pump	\$	255.00	✓
49	1	Front right knuckle arm	\$	465.00	✓
50	1	Front right axle beam	\$	1,560.00	✓
51	1	Front right trailing link	\$	246.00	✓
52	1	Front right anti roll bar	\$	455.00	✓
53	1	Front right wheel hub with bearing	\$	350.00	✓
54	1	Front right shock absorber assy	\$	650.00	✓
55	1	Front right leaf spring assy	\$	1,567.00	✓
56	1	Front right tie rod	\$	191.00	✓
			\$	35,201.00	
less 15%			\$	5,280.15	
			\$	29,920.85	

8126.40
6967.44

Special Nett Items

1	6	Front grille clips	\$ nec	50.00	20
2	12	Front bumper clips	\$ nec	60.00	30
3	6	Front right door inner step board clips	\$ nec	40.00	7 30
4	8	Front right door inner trim board clips	\$ nec	40.00	8 30
5	1	Front windscreen glass sealant	\$ nec	100.00	60
6	1	Front 'ERP' unit	\$	180.00	✓ un
7	1	Front 'ERP' unit bracket	\$	35.00	un
8	1	Front right tyre	\$	350.00	✓ un
9	1	Front right wheel rim	\$	650.00	✓ un
10	1	Front no plate	\$	100.00	h 30
11	1	Front panel "Reward NN" sticker	\$	100.00	nec 40
			\$	1,705.00	
Total parts			\$	31,625.85	245

YP5022Z Isuzu Reward

No. [REDACTED] Description [REDACTED]

1	Labour for panel beating, cut, weld, straighten front and front right affected area and replace front and front right damaged parts.	\$ 3,200.00	1300.
2	To putty and spray painting front and front right portion.	\$ 3,200.00	1300
3	To check wiring and focus front headlamp.	\$ 50.00	30.
4	To apply anti rust proofing to front and front right affected area.	\$ 140.00	50
5	To remove and install front right undercarriage parts.	\$ 350.00	X
6	To balance front right wheel.	\$ 50.00	X
7	To conduct wheel alignment.	\$ 120.00	X
8	To remove and install front right wing mirror for function.	\$ 120.00	30
9	To remove and install front right door lock mechanism.	\$ 80.00	20
10	To check front right door central locking for function.	\$ 80.00	7
11	To transfer front right door glass to new door.	\$ 80.00	30
12	To remove and install front right door regulator with motor assy.	\$ 80.00	30
13	To clean and vacuum the glass debris in the interior of the car.	\$ 140.00	120.
14	To remove and install front windscreen glass to facilitate the repair.	\$ 300.00	X un
15	To remove and install front brake booster and clutch master pump.	\$ 300.00	X un
16	To remove and install front steering column assy.	\$ 80.00	30
17	To remove and install front view camera.	\$ 180.00	X un
18	Towing service.		

Total labour : \$ 8,630.00

2960.

Total parts : \$ 31,625.85

Total labour : \$ 8,630.00

Total repair cost : \$ 40,255.85

Tanpin 97495749

6907.44

'up' 27/11/21 @ 450pm

245

c/s Resurvey after repair.

2960

09 days

10112.44

Tanpin c/s Resurvey

c/s 8050

09 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: