

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CHAN'S & SONS ENTERPRISE 363 SEMBAWANG ROAD GOODLINK PARK SINGAPORE 758379 Contact No	Cust No/Name / CHAN'S & SONS ENTERPRISE Reg No/Reg Date SMF2085G / 31/10/201 Date In/Mileage / 0 Chassis No KNAF1416MK5019017 Engine No G4FGJH709903 Make/Model KIA/CERATO 1.6 A L S065 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	22/11/2021/ 11:49	TLC	442 / CocoLu	42797			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E PNT88000	RENEW FRT BUMPER, FRT FENDER LH							800.00
E PNT98000	SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH							700.00
B WHEELALIGNMENT	To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY	TRANSFER FRT LEFT RIM							30.00
M SUNDRY	SUPPLY FRT LEFT RIM							360.00
A 90000001	CHECK WIRING & ELECTRICAL SYSTEM							30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							120.00
M SUNDRY	Sundry							20.00
A 90000001	RENEW FRT UNDER CARRIAGE							300.00
M COVER-FR BUMPER					1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER					1.00	262.00	00.00	262.00
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	22.00	00.00	22.00
M PANEL-FENDER, LH					1.00	430.00	00.00	430.00
M HUB ASSY-FR WHEEL					1.00	436.00	00.00	436.00
M ARM COMPLETE-FR LWR, LH					1.00	286.00	00.00	286.00

Estimate

Steve (LKK)

22/11/21, 4.30p

wil PL

P/P

M BIL M

5 dys

LKK Auto Consultants hence notify the Repairer of the following:

Estimate

Store (LKK)

22/11/21, 4.30pm

wil PL

P/P

M B/L M
5 dys

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

7% GST on

Nett 4,549.00
318.43

Total Payable 4,867.43

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.