

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	22 Nov 2021 19:42	Clm Veh Model Changed		[] Merimen Administrator
2	22 Nov 2021 19:42	Clm Created	Reg No: SMF2257C. Policy No: 1800128102-02. Acct Date: 2021/11/19. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SC1A21BM0003	[I] Merimen Administrator
3	23 Nov 2021 09:01	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	23 Nov 2021 09:01	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	23 Nov 2021 09:01	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	23 Nov 2021 09:01	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/12/02	[A] LEE SU THING
7	23 Nov 2021 09:01	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] LEE SU THING
8	23 Nov 2021 09:01	Clm Registration Modified	Rep:1137->200074.	[A] LEE SU THING
9	23 Nov 2021 09:01	Clm Veh Model Changed	(205158) KIA CERATO 1.6 (A).	[A] LEE SU THING
10	23 Nov 2021 09:01	Adj Adjuster Assigned	[None] -> CHEN TSUE YEE	[A] LEE SU THING
11	23 Nov 2021 13:00	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	23 Nov 2021 13:00	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	23 Nov 2021 13:00	Clm Dtl Modified	JPJ Reg. Date: -> 2018/10/31.	[A] Elaine Kuan Hwa Meen
14	23 Nov 2021 13:00	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	23 Nov 2021 14:07	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/12/02	[A] SHIAU CHAN
16	23 Nov 2021 14:07	Adj Mandate Request	Cur.Req:10967.60:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REP AIR.	[A] SHIAU CHAN
17	23 Nov 2021 14:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/12/02. Mandate Remarks: await policy coverage, retake damage no 30-33 photo "ULTRASONIC SENSOR ASSY-BWS" Re-inspection require on hidden part, check item, supplementary part with clear photo. Note: Before painting photo	[I] Chang, Lois-KL
18	23 Nov 2021 14:31	Adj Mandate Set	Approved:6869.00:await policy coverage, retake damage no 30-33 photo "ULTRASONIC SENSOR ASSY-BWS" Re-inspection require on hidden part, check item, supplementary part with clear photo. Note: Before painting photo require (all welded panel and repa	[I] Chang, Lois-KL
19	23 Nov 2021 17:00	Clm Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 0.00. Excess Waived: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Abu Kassim, Noor Mariesa

Date From   
 Date To   
 Audit Type 

ACTIVITY

No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2742997	23 Nov 2021 13:00:10	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMF2257C		11.00

