

NS

BIFROST AUTO PTE LTD
8 KAKI BUKIT AVE 4 #01-49
SINGAPORE 415875
TEL: 64524457 FAX: 64524584
ATT: IKHWAN HP 93290237

Estimate for SKH8852H(Mitsubishi Lancer)

- 1 *BONNET
- 1 *FRONT BUMPER
- 1 *FRONT BUMPER RETAINER LH
- 1 *FRONT BUMPER MITSUBISHI LOGO
- 1 *FRONT FOGLAMP COVER LH
- 1 *FRONT FOGLAMP LH
- 1 *HEADLAMP LH
- 1 *HEADLAMP LOWER BRACKET LH
- 1 *FRONT FENDER LH
- 1 *FRONT FENDER INNER SHIELD LH
- 1 *FRONT LOWER ARM LH
- 1 *FRONT KNUCKLE ARM LH
- 1 *FRONT ABSORBER LH
- 1 *FRONT STABILIZER LINK LH
- 1 *FRONT TIE ROD LH
- 1 *FRONT WHEEL BEARING LH
- 1 *FRONT DRIVESHAFT LH

Less 10%

	2013	
	\$1,326.30	NDX
858.00	\$955.40	CuTV
25.40	\$62.20	NECV
43.00	\$82.80	NECV
	✓ \$58.00	DL ✓
	\$102.00	NDX
	✓ \$791.00	CuTV
	\$77.80	NSX
588.00	\$908.00	DD ✓
	\$201.90	NDX
	\$303.10	
	\$503.80	
	\$515.20	
	\$123.90	NDX
	\$98.10	
	\$118.70	
	\$1,390.00	
2,363.40	\$7,618.20	
236.34	\$761.82	
2,127.06	\$6,856.38	
	\$850.00	NDX
30.00	\$50.00	NECV
	\$50.00	NNX
	\$95.00	NDX
	\$1,045.00	

- 1 *FRONT SPORT RIM
- 1 *FRONT BUMPER CLIPS
- 1 *FRONT FENDER SPLASH SHIELD CLIP
- 1 *LH FRONT TYRE

TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE
REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND
REPLACED THE DAMAGED PARTS AND COMPONENTS
BEFORE AND AFTER WHEEL ALIGNMENT
LABOUR FOR UNDERCARRIAGE
TO RESPRAY UNDERCOATING ON PARTS REPLACED
TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS
REPLACED

\$1,000.00	600.00 ✓
\$100.00	
\$250.00	NNX
\$200.00	
\$1,000.00	400.00
\$150.00	NNX
\$2,700.00	

TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS

Signature: _____
Date: _____
Acknowledged by Repairer: _____
Total

Survey & Resurvey
23/11/2021
1140 hrs
TGMW
Lump sum repair
Repair days 5

\$10,601.38

PARTS	3127.06
SN	30.00
Labour	1000.00
	3157.06
@20%	631.41
	2,525.65