

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

Auto & General Southeast Asia (SEA)
190 Clemenceau Ave, #03-01
Singapore Shopping Centre
Singapore 239924
Attn: Motor Claim Department

*Not Notation
11 Pm @ 1000h
Resurvey After Paint
2 days*

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SKA5127A

MODEL : TOYOTA Camry 2.0

POLICY NO :

CHASSIS NO : MR053BK4107016818

YEAR OF MANUFACTURE : 2008

DATE / TIME OF ACCIDENT: 05/11/2021 Time: 1851Hrs at Lentor toward Yishun

THIRD PARTY VEHICLE NO: SKLP7580U

Date: 22/11/2021

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	8F940-06914	Quantity	Unit Price	Amount
			S\$	S\$
1	FRONT MIRROR COMPLETE SET LH		1,159.70	CM 1,159.70 ✓
2	FRONT DOOR LH		1,620.00	R 1,620.00 X

Sub-Total: 2,779.70

Less: 25% discount - 694.93

Total Parts after 25% discount: 2,084.78

Special Nett Items

1	ANTI-RUST COATING	1	80.00	nn 80.00 X
				80.00

Total Parts: 2,164.78

Labour Charges For Front

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	600.00	12d
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	600.00	28d
3	Provide skill labour to disconnect and check electrical wiring	150.00	2d
4	Dismantle and transfer door and mechanism to facilitate repair	nn 120.00	X

Total Labour:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Parts & Labour:

GST 7%

Grand Total:

1,470.00

3,634.78

254.43

3,889.21

Estimate Repair Duration

5 days