

TP Budget Direct PC7556L 2018 Nov

Xiao Chen Toyota Hilux 2982CC

JTFST22P400038070

Rear Bumper Reformed

517.20 ✓

Rear Bumper Clips. New

30(SN) ✓

Rear Bumper Side Holder x 02 Dented $55.4 \times 2 = 110.80$ ✓

Rear Bumper Lower Bracket x 04 Bent $22 \times 4 = 88$ ✓

Reverse Sensor (Set of 4) Dented $380(\text{SN})^{280(\text{SN})}$

Rear End Panel Outer. Dented 581.50 ✓

Rear End Panel Inner Repair 654.30 X

Rear End Panel Top Metal Piece. ^{new} 110.50 X

Rear End Panel Sealant. New 60(SN) ^{368.30} ✓

Taillamp x 02 LH cracked $368.3 \times 2 = 736.60$

Taillamp Panel LH. Repair 545.10 X

Taillamp Lower Apron x 02 ^{LH cracked} 84.60
 $84.6 \times 2 = 169.20$

Tailgate Dented

2151.10 ✓

PC 7556L

Tailgate lock ^{key} 293.70 ✓

~~Tailgate Lock Actuator~~

Tailgate Weatherstripe. ^{cut} 381.90 ✓

Tailgate Inner Trim Board } ^{NEC} 175.80 X

Tailgate Inner Trim Board clips } ^{NEC} 30(SN) X

Tailgate G/s Moulding } ^{NEC} 201.40 ✓

Tailgate G/s Sealant } ^{NEC} 60(SN) ✓

Toyota Logo. } ^{NEC} 55 ✓

Toyota Hiace Sticker } ^{NEC} 32 ✓

Emergency Door Sticker } ^{NEC} 22 ✓

70km/h Sticker } ^{NEC} 15(SN) ✓

Spare Tyre Carrier } ^{NEC} 263.50 X

Spare Tyre Carrier Bolt } ^{NEC} 35. X

PC 7556L.

Panel Beating	1200 800
Spray Painting	1200 800
Wiring.	50 30
To remove reverse sensor	100 50
To spray tuff coat.	150 60
To transfer tailgate fittings	150 80
To remove tailgate g/l's	180 120.

list: 4891.50

Len 25%: 3668.62

S.N: 945

Labour: 1940

total: 6053.62

h/s: 4.8K

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: