

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street

IOB Building #04-05

Singapore 049711

TEL: 63476100

FAX: 62244174 , 62257743

ATTN: Motor Claim Department \ INDIA

Your Ref No: TP 1121-6559

Claim Type: Third Party

Accident Date: 20/11/2021

TP Veh Reg No: SMV 6131 X

Estimate No: EST1507559

Date: 22 Nov 2021

Policy No: GA556498

Veh Reg No: **SMG6862Z**

Make/Model: TOYOTA ALTIS

Chassis No: -MR053REH604594302

Engine No: 1ZR0C77422

Reg. Date: 28/12/2018

Estimate Repair Cost to Vehicle No :SMG6862Z

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	486.0000	1 PC	486.00	
2 REAR BUMPER SIDE HOLDER - LH/RH	110.0000	2 PC	220.00	
3 REAR BUMPER SIDE BRACKET - LH/RH	63.0000	2 PC	126.00	
4 REAR BUMPER CLIPS	5.0000	10 PC	50.00	
5 REAR BUMPER REINFORCEMENT	395.0000	1 PC	395.00	
6 REAR BUMPER REFLECTOR - LH/RH	63.0000	2 PC	126.00	
7 REAR BOOT	755.0000	1 PC	755.00	
8 REAR BOOT INSULATOR	455.0000	1 PC	455.00	
9 REAR BOOT TOP LOCK	382.0000	1 PC	382.00	
10 REAR BOOT BOTTOM LOCK	30.0000	1 PC	30.00	
11 REAR BOOT TOYOTA EMBLEM	78.0000	1 PC	78.00	
12 REAR BOOT COROLLA ALTIS WORDING	70.0000	1 PC	70.00	
13 REAR BOOT HINGE - LH/RH	70.0000	2 PC	140.00	
14 REAR BOOT CHROME MOULDING	435.0000	1 PC	435.00	
15 REAR BOOT LAMP - LH/RH	401.0000	2 PC	802.00	
16 REAR BOOT RUBBER	185.0000	1 PC	185.00	
17 REAR BUMPER SENSOR	180.0000	2 PC	360.00	
18 REAR TAILLAMP - LH/RH	395.0000	2 PC	790.00	
19 REAR TAILLAMP CLIP - LH/RH	6.0000	2 PC	12.00	
20 REAR PANEL	560.0000	1 PC	560.00	
21 REAR PANEL TOP GARNISH	240.0000	1 PC	240.00	
22 REAR PANEL TOP GARNISH CLIP	5.0000	4 PC	20.00	
23 REAR SPARE TYRE BOARD	267.0000	1 PC	267.00	
24 REAR FENDER INNER GARNISH - LH/RH	320.0000	2 PC	640.00	
25 ANTENNA KEY SENSOR	161.0000	1 PC	161.00	
26 REAR FLOOR PANEL	797.0000	1 PC	797.00	
27 REAR EXHAUST	939.0000	1 PC	939.00	
28 REAR EXHAUST INSULATOR	135.0000	1 PC	135.00	
29 FRONT BONNET LOCK	130.0000	1 PC	130.00	
30 FRONT GRILLE ASSY WITH LOGO AND CHROME GARNISH	564.0000	1 PC	564.00	
31 FRONT GRILLE TOP GARNISH	135.0000	1 PC	135.00	
32 FRONT GRILLE TOP GARNISH CLIP	5.0000	4 PC	20.00	
33 FRONT HEADLAMP - LH/RH	3,879.0000	2 PC	7,758.00	
34 FRONT BUMPER	514.0000	1 PC	514.00	
35 FRONT BUMPER SIDE HOLDER - LH/RH	105.0000	2 PC	210.00	
36 FRONT BUMPER CLIPS	5.0000	10 PC	50.00	
37 FRONT BUMPER LOWER GRILLE	188.0000	1 PC	188.00	
38 FRONT BUMPER FOGLAMP GARNISH - LH/RH	177.0000	2 PC	354.00	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street

IOB Building #04-05

Singapore 049711

TEL: 63476100

FAX: 62244174 , 62257743

ATTN: Motor Claim Department \ INDIA

Your Ref No: TP 1121-6559

Claim Type: Third Party

Accident Date: 20/11/2021

TP Veh Reg No: SMV 6131 X

Estimate No: EST1507559

Date: 22 Nov 2021

Policy No: GA556498

Veh Reg No: **SMG6862Z**

Make/Model: TOYOTA ALTIS

Chassis No: -MR053REH604594302

Engine No: 1ZR0C77422

Reg. Date: 28/12/2018

Estimate Repair Cost to Vehicle No :SMG6862Z

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
39 FRONT BUMPER REINFORCEMENT	382.0000	1 PC	382.00	
40 FRONT BUMPER FOAM	108.0000	1 PC	108.00	
41 FRONT SUPPORT PANEL	989.0000	1 PC	989.00	
42 CONDENSER	1,820.000	1 PC	1,820.00	
43 CONDENSER SIDE GARNISH - LH/RH	0.0000	2 PC	0.0000	
44 RADIATOR	2,169.000	1 PC	2,169.00	
45 BRACE PANEL	155.0000	1 PC	155.00	
			25,202.00	
		Less 25%	6,300.50	18,901.50
Special Net				
46 FRONT NUMBER PLATE WITH CASING	35.0000	1 PC	35.00	
47 REAR NUMBER PLATE WITH CASING	35.0000	1 PC	35.00	
48 COOLANT	50.0000	1 PC	50.00	
ANY			120.00	120.00
Labour				
49 TO KNOCK OUT DENTS, CUT/WELD FRONT SUPPORT PANEL, REAR PANEL, REAR FLOOR PANEL, REMOVE, REPLACE ACCIDENT PARTS	2,200.000	1 JOB	2,200.00	
50 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,800.000	1 JOB	1,800.00	
51 TO REMOVE, REFIX CONDENSER AND REFILL GAS	100.0000	1 JOB	100.00	
52 TO CHECK WIRING (REAR AND FRONT)	50.0000	1 JOB	50.00	
53 TO TUFF-KOTE	120.0000	1 JOB	120.00	
54 TO REMOVE, REPLACE REAR BUMPER SENSOR	80.0000	1 JOB	80.00	
55 TO REMOVE, REFIX INNER GARNISH TO FACILITATE REPAIRS	150.0000	1 JOB	150.00	
56 TO REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	150.0000	1 JOB	150.00	
57 TO REMOVE, REFIX REAR EXHAUST PIPE	150.0000	1 JOB	150.00	
58 TO 4 WHEEL ALIGNMENT	100.0000	1 JOB	100.00	
			4,900.00	4,900.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street

IOB Building #04-05

Singapore 049711

TEL: 63476100

FAX: 62244174 , 62257743

ATTN: Motor Claim Department \ INDIA

Your Ref No: TP 1121-6559

Claim Type: Third Party

Accident Date: 20/11/2021

TP Veh Reg No: SMV 6131 X

Estimate No: EST1507559

Date: 22 Nov 2021

Policy No: GA556498

Veh Reg No: **SMG6862Z**

Make/Model: TOYOTA ALTIS

Chassis No: -MR053REH604594302

Engine No: 1ZR0C77422


Reg. Date: 28/12/2018

Estimate Repair Cost to Vehicle No :SMG6862Z

Description	U/Price	Quantity	Price	Amount
			S\$	S\$
		Total		S\$ 23,921.50
		Add GST @ 7%		1,674.51
		Total Amount Payable		<u>S\$ 25,596.01</u>

TOTAL: SINGAPORE DOLLAR TWENTY FIVE THOUSAND FIVE HUNDRED NINETY SIX AND CENTS ONE ONLY

For Progressive Car Care Pte Ltd


AUTHORISED SIGNATURE