

Not Authorized

2/5 \$ 13,000
10 day

26 November 2021

REG NO.: SFF 2969 P
MAKE/MODEL: TOYOTA WISH

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Front bonnet <i>bu c</i>	745 \$ 922.80
2	Front bonnet hinges <i>n/s bent o/s R</i>	48.75 \$ 97.50 <i>1 pc</i>
2	Front headlamps - HID <i>3 no/cne</i>	1860 x 2 = 3720 \$ 4,626.20
1	Front grille <i>11</i>	\$ 107.32 <i>X</i>
1	Front bumper <i>Dis</i>	671 \$ 981.25
2	Front bumper fog lamps <i>n/s cne o/s 11</i>	260 \$ 539.80 <i>1 pc</i>
1	Front bumper inner sponge <i>Torn</i>	\$ 120.69
1	Front bumper reinforcement <i>Bent</i>	\$ 345.65
1	Front bumper side grille. <i>n/s Dis</i>	\$ 97.90
2	Front bumper side retainers <i>cne</i>	\$ 97.70
2	Front fenders <i>DD/buc</i>	\$ 1,577.02
2	Front fender lower stays <i>11</i>	\$ 179.00 <i>X</i>
2	Front fender inner shields <i>Torn</i>	\$ 322.50
1	Front fender wheel housing panel - LH <i>body m</i>	\$ 596.50
1	Air con condenser <i>11</i>	\$ 1,404.90 <i>X</i>
1	Radiator <i>11</i>	\$ 1,876.65 <i>X</i>
1	Air cleaner box <i>cne</i>	\$ 295.20
1	Air intake duct <i>cne</i>	\$ 135.80
1	Battery bracket <i>Bent</i>	\$ 225.20
1	Fuse box assy <i>cne</i>	\$ 382.60
1	Front wiper tank <i>11</i>	\$ 189.20 <i>X</i>
1	Wiper garnish (1 set) <i>Dis</i>	315 \$ 483.00
1	Front support panel <i>Bent/11</i>	972.25 \$ 1,155.69
1	Front brace panel <i>11</i>	\$ 111.05 <i>X</i>
1	Front wheel hub: <i>n/s Bent</i>	322 \$ 413.00
1	Front wheel bearing <i>n/s</i>	150 \$ 258.60
1	Front shock absorber. <i>n/s Bent</i>	485 \$ 853.00
1	Front tie rod: <i>n/s</i>	11 \$ 230.40 <i>X</i>
1	Front knuckle arm: <i>n/s Bent</i>	490 \$ 823.00
1	Front lower arm. <i>n/s Buc</i>	681 \$ 891.20
1	Power steering rack <i>11</i>	\$ 1,483.30 <i>X</i>
1	Power steering rack cross member <i>Bent/11</i>	1415 \$ 1,855.70
1	Front stabilizer bar <i>11</i>	\$ 385.00 <i>X</i>
2	Front stabilizer bar links <i>11</i>	\$ 237.30 <i>X</i>
1	Drive shaft RH <i>11</i>	\$ 1,584.60 <i>X</i>
1	Drive shaft LH <i>11</i>	\$ 1,584.60 <i>X</i>
		\$ 27,470.82

	c/f:	\$	27,470.82	
2	Front doors <i>R</i>	\$	2,593.30	<i>X</i>
2	Front door glass outer mouldings <i>11</i>	\$	253.00	<i>X</i>
2	Front door lower chrome garnishes <i>11</i>	\$	644.00	<i>X</i>
2	Front door rubbers <i>11</i>	\$	248.90	<i>X</i>
1	Front door side mirror - RH <i>R</i>	\$	987.65	<i>X</i>
		\$	32,197.67	
1	front windscreen <i>one \$1105.20</i>	Less 25%	\$	8,049.42
1	front windscreen moulding <i>new \$168.50</i>		\$	24,148.25
<u>SPECIAL NETT ITEMS</u>				
2	Front fender inner shield clip (2 set) <i>new</i>	\$	100.00	<i>40</i>
1	Battery <i>Dange</i>	\$	280.00	<i>100</i>
2	Front tyres <i>NLS cur 42200 602 = 1205/N</i>	\$	800.00	<i>120</i>
2	Front wheel rims <i>NLS 015 cur 12c 4005/N</i>	\$	800.00	<i>420</i>
1	Rocker panel side skirt - RH <i>Turn</i>	\$	450.00	<i>✓</i>
1	front windscreen sealant <i>new 405/N</i>	\$	2,430.00	
<u>LABOUR CHARGES</u>				
1	To check wiring and reset headlamps focusing.	\$	80.00	<i>30</i>
2	To remove and refit front undercarriage.	\$	500.00	<i>300</i>
3	To conduct wheel alignment.	\$	180.00	<i>60</i>
4	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$	180.00	<i>80</i>
5	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$	400.00	<i>11 X</i>
6	To apply undercoating.	\$	200.00	<i>50</i>
7	Panel beating.	\$	2,500.00	<i>1400</i>
8	To re-spray painting on the affected areas.	\$	2,400.00	<i>1500</i>
9	To R & R front windscreen <i>120 ✓</i>	\$	6,440.00	

GRAND TOTAL :

\$ 33,018.25

1-15899-46
252
11774.59

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: