



Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

26 November 2021

REG NO.: SFF 2969 P
MAKE/MODEL: TOYOTA WISH

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bonnet	\$ 922.80 DT 798.8
2	Front bonnet hinges LH-BT RH-SVC	\$ 49.75 97.50 DIS ✓
2	Front headlamps - HID	\$ 4,626.20 3079.56 Cra
1	Front grille	\$ 107.32 Cut
1	Front bumper	\$ 981.25 Cut 692
2	Front bumper fog lamps	\$ 539.80 Cra
1	Front bumper inner sponge	\$ 120.69 Cut
1	Front bumper reinforcement	\$ 345.65 DT 295.3
2	Front bumper side grilles	\$ 97.90 Cut
2	Front bumper side retainers	\$ 97.70 nec
2	Front fenders	\$ 1,577.02 Df
2	Front fender lower stays	\$ 179.00 nec LH
2	Front fender inner shields	\$ 322.50 161.25 cut RH
1	Front fender wheel housing panel - LH	\$ 596.50 XH / DT
1	Air con condenser	\$ 1,404.90 XH X SVC
1	Radiator	\$ 1,876.65 XH X SVC
1	Air cleaner box	\$ 295.20 Cut
1	Air intake duct	\$ 135.80 Cut
1	Battery bracket	\$ 225.20 BT
1	Fuse box assy	\$ 382.60 CRA
1	Front wiper tank	\$ 189.20 MS 80
1	Wiper garnish (1 set)	\$ 483.00 Cut 210
1	Front support panel	\$ 1,155.69 XV
1	Front brace panel	\$ 111.05 XV
2	Front wheel hubs	\$ 413.00 X SVC
2	Front wheel bearings	\$ 258.60 DIS 124.3
2	Front shock absorbers	\$ 853.00 RH SVC 250 LH 124.3
2	Front tie rods	\$ 230.40 X SVC
2	Front knuckle arms	\$ 823.00 X SVC
2	Front lower arms	\$ 891.20 RH SVC 367.4 LH BT
1	Power steering rack	\$ 1,483.30 X SVC
1	Power steering rack cross member	\$ 1,855.70 X SVC
1	Front stabilizer bar	\$ 385.00 X SVC
2	Front stabilizer bar links	\$ 237.30 X SVC
1	Drive shaft RH	\$ 1,584.60 X SVC
1	Drive shaft LH	\$ 1,584.60 X SVC
		\$ 27,470.82

	c/f:	\$	27,470.82
2	Front doors	\$	2,593.30 Xr
2	Front door glass outer mouldings	\$	253.00 XsVC
2	Front door lower chrome garnishes	\$	644.00 XsVC
2	Front door rubbers	\$	248.90 XsVC
1	Front door side mirror - RH	\$	DTS 987.65 /
		\$	32,197.67
	Less 25%	\$	8,049.42
		\$	24,148.25

SPECIAL NETT ITEMS

2	Front fender inner shield clip (2 set)	\$	100.00 40
1	Battery	\$	280.00 180
2	Front tyres	LHsVC \$	LH Cut 800.00 XsVC 12060/6
2	Front wheel rims	\$	800.00 Scr
1	Rocker panel side skirt - RH	\$	Cut 450.00 /
		\$	2,430.00

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00 30
2	To remove and refit front undercarriage.	\$	500.00 100
3	To conduct wheel alignment.	\$	180.00 60
4	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$	180.00 80
5	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$	400.00 XNN
6	To apply undercoating.	\$	200.00 50
7	Panel beating.	\$	2,500.00 1200/400
8	To re-spray painting on the affected areas.	\$	2,400.00 1200
		\$	6,440.00

GRAND TOTAL :

\$ 33,018.25

F: 10400
RD: 7

thuan@ckhauto.com
82235769
23/11/21 1500
7 days wp
L/S after repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: