

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21011901/APA3Q2**Date:** 01/09/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : SJH5714E **Insured Vehicle No :** GBL240L

Date of Loss: 19/11/2021 Nature of Claim: TP Claim No: MFL2021D0005140

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH5714E**

Make & Model: AUDI TTC, 2.0 TFSI S-TRONIC (A) Engine No: BWA196233

Reg. Date: 13/08/2008 (Man. Year: 2007) Chassis No: TRUZZZ8J981026560

Colour: Grey Odometer: 134156 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	60,817.26	23,053.85	37,763.41	62.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,230.00	3,850.00	4,380.00	53.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	69,047.26	26,903.85	42,143.41	61.04
Approved Total (Overridden) (S\$)		21,400.00		
(S\$)	69,047.26	21,400.00	47,647.26	69.01
+ GST 7.00/7.00% (S\$)	4,833.31	1,498.00	3,335.31	69.01
Nett Amount (S\$)	73,880.57	22,898.00	50,982.57	69.01
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 22/11/2021

Date Inspected: 24/11/2021 Inspected At:

RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @
KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 11.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2022)
Parts:	M1-COUPE	AUDI TTC 2.0 TFSI S-TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH5714E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP RH	Not Necessary	2,900.00 FL	*- FL
2	1		*HEAD LAMP BOTTOM RETAINER RH	Not Necessary	273.10 FL	*- FL
3	1		*FRONT BUMPER	Not Necessary	2,542.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	189.40 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP	Not Necessary	485.00 FL	*- FL
6	1		*FRONT BUMPER FOG COVER RH	Not Necessary	258.00 FL	*- FL
7	1		*BONNET	Not Necessary	2,415.00 FL	*- FL
8	2		*BONNET HINGE	Not Necessary	490.00 FL	*- FL
9	1		*FRONT FENDER RH	Not Necessary	1,258.00 FL	*- FL
10	1		*FRONT FENDER COWLING RH	Not Necessary	276.50 FL	*- FL
11	1		*FRONT ABSORBER RH	Not Necessary	890.70 FL	*- FL
12	1		*FRONT LOWER ARM RH	Not Necessary	920.90 FL	*- FL
13	1		*FRONT KNUCKLE ARM RH	Not Necessary	1,000.70 FL	*- FL
14	1		*FRONT WHEEL BEARING RH	Not Necessary	688.80 FL	*- FL
15	1		*FRONT DOOR RH	Dented	3,600.60 FL	*3,600.60 FL
16	1		*FRONT DOOR INNER PILLAR RH	Repair	897.20 FL	*- FL
17	1		*FRONT DOOR OUTER PILLAR RH	Repair	925.80 FL	*- FL
18	2		*FRONT DOOR HINGE RH	Not Necessary	508.00 FL	*- FL
19	1		*FRONT DOOR CHEAKER RH	Not Necessary	277.40 FL	*- FL
20	1		*FRONT DOOR OUTER MOULDING RH	Not Necessary	298.00 FL	*- FL
21	1		*FRONT DOOR SIDE MIRROR ASSY RH	Damaged	1,584.00 FL	*1,584.00 FL
22	1		*FRONT DOOR OUTER HANDLE RH	Repair	327.00 FL	*- FL
23	1		*FRONT DOOR OUTER HANDLE COVER RH	Not Necessary	112.20 FL	*- FL
24	1		*FRONT DOOR INNER LOCK RH	Not Necessary	417.50 FL	*- FL
25	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	36.00 FL	*- FL
26	1		*FRONT DOOR FRAME WEATHERSTRIP RH	Necessary	452.00 FL	*452.00 FL
27	1		*FRONT DOOR CHANNEL RH	Not Necessary	178.60 FL	*- FL
28	1		*FRONT DOOR REGULATOR MOTOR RH	Not Necessary	685.00 FL	*- FL
29	1		*FRONT DOOR REGULATOR GEAR RH	Not Necessary	595.00 FL	*- FL
30	1		*FRONT DOOR INNER TRIM RH	Not Necessary	1,688.80 FL	*- FL
31	1		*FRONT DOOR STEP GARNISH	Not Necessary	422.50 FL	*- FL
32	1		*FRONT DOOR STEP GARNISH INNER	Not Necessary	485.00 FL	*- FL
33	1		*SIDE SKIRT RH	Deformed	999.90 FL	*999.90 FL
34	1		*ROCKER PANEL	Repair	1,546.00 FL	*- FL
35	1		*FRONT DRIVER SEAT BELT	Activated	890.00 FL	*890.00 FL
36	1		*SRS AIR BAG CONTROL UNIT	Activated	1,788.30 FL	*1,788.30 FL
37	1		*REAR FENDER RH	Distorted	8,889.70 FL	*8,889.70 FL
38	1		*REAR FENDER GLASS WITH MOULDING RH	Cut	1,124.00 FL	*1,124.00 FL
39	1		*REAR FENDER COWLING RH	Not Necessary	325.40 FL	*- FL
40	1		*REAR FENDER INNER TRIM RH	Not Necessary	980.30 FL	*- FL
41	1		*FUEL LID COVER	Not Necessary	427.20 FL	*- FL
42	1		*REAR ABSORBER RH	Bent	699.80 FL	*699.80 FL
43	1		*REAR UPPER ARM RH	Bent	555.80 FL	*555.80 FL
44	1		*REAR LOWER ARM RH	Bent	666.60 FL	*666.60 FL
45	1		*REAR CONTROL ARM RH	Bent	498.70 FL	*498.70 FL
46	1		*REAR TORSION ARM RH	Bent	488.60 FL	*488.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR KNUCKLE ARM RH	Damaged	999.80 FL	*999.80 FL
48	1		*REAR WHEEL BEARING RH	Damaged	788.70 FL	*788.70 FL
49	2		*WHEEL RIM	O/S Rear Cut	7,398.60 FS	*1,200.00 FS
50	1		*TAIL LAMP RH	Not Necessary	1,788.90 FL	*- FL
51	1		*REAR BUMPER	Not Necessary	1,544.30 FL	*- FL
52	2		*REAR BUMPER SIDE RETAINER	Not Necessary	560.00 FL	*- FL
53	1		*FRONT BUMPER CLIP	Not Necessary	50.00 FS	*- FS
54	1		*FRONT FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS
55	1		*FRONT DOOR STEP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
56	1		*SET FRONT DOOR INNER TRIM CLIP	Not Necessary	40.00 FS	*- FS
57	1		*FRONT DOOR INNER PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
58	1		*FRONT DOOR OUTER PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
59	1		*SIDE SKIRT CLIPS	Necessary	50.00 FS	*50.00 FS
60	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*50.00 FS
61	1		*REAR FENDER GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
62	1		*SET REAR FENDER COWLING CLIP	Necessary	40.00 FS	*30.00 FS
63	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
64	1		*REAR FENDER QUARTER GLASS SEALANT	Repeated	60.00 FS	*- FS
65	1		*REAR FENDER QUARTER GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
66	1		*SET TAIL LAMP BULB	Not Necessary	40.00 FS	*- FS
67	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
68	2		*WHEEL TYRE RH	Not Necessary	1,600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	63,499.30	25,456.50
- List Item Discount on L Items 5.00/10.00% (\$)	2,682.04	2,402.65
Total Parts (\$)	60,817.26	23,053.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,500.00	1,500.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,500.00	1,500.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	250.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	200.00	60.00
5	REMOVE AND INSTALL CARPET ,SEAT AND INTERIOR	New	500.00	120.00
6	REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	600.00	0.00
7	REMOVE AND INSTALL REAR UNDER CARRIAGE	New	600.00	250.00
8	TO CHECK FOUR WHEEL ALIGNMENT	New	80.00	80.00
9	REMOVE AND INSTALL FRONT DOOR PART	New	250.00	100.00
10	REMOVE AND INSTALL REAR FENDER GLASS	New	250.00	60.00
11	TO RESET AND REPROGRAM AIR BAG SYSTEM AND FUNCTION	New	500.00	150.00
Gross Labour Cost (\$\$)			8,230.00	3,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >