

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bol. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3-Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

MV-65K

Date/Time File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (\$

☐

: Wash and

Survey Fee:

Transportation:

\$ + P.S. \$

Finishes

Labour

Total

Veh No:

FBS3609B

Yr Regn:

31/3/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Ducati Multistrada

c.c. 1260

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

6563

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

2DM1A00AAMB001860

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

170/70ZR19

R:

170/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

17/11/21

D.O.A.

23/11/21

Survey held at

Wearnes

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/tp or

The U/C / Chassis frame / Body Structure affected due to collision.

SERVICE ESTIMATE

92615 - CO 001 SL: SERVICE SALES - PC
Wearnes Automotive Pte. Ltd. (DUCATI)
Attn: After Sales/Service

Inv.No. .. : D 0 Page 1
Inv.date .. : 22/11/2021
WIP No. .. : 55328
Veh. In/Out:
*Tel.No. .. : Work: 63782628
Reg.No. .. : FBS3609B / MTS V4
Reg.date .. : 31/03/2021
Mileage .. : 0
Chassis No.: ZDM1A00AAMB001860
Variant... : MTS V4 S FULL

Closed by : Tony Alfred Desire D
Svc Consultant : 0988
Remarks : Wearnes Automotive P

Op.No	Description	CCC Mech Qty	Price	Disc%	Pkg	Amount	G
DUCT-A	Accident Damage Assessment		70.00	0		70.00	S X
NOTES	acc		0.00	0			S
DUCO-1	To replace damaged parts caus	1230 x 3	3600.00	0		3600.00	S ✓
	Required to dismantle rear chassis, swing arm and other parts (+ take photo)						
	NUMBER PLATE SU	1.0 EA	64.40			64.40	S
	NUMBER PLATE SU	1.0 EA	57.50			57.50	S
	REAR WHEEL RIM	1.0 EA	2331.80			2331.80	S
	TRANSFER	1.0 EA	18.40			18.40	S
	PLATE	1.0 EA	218.30			218.30	S
	REAR FRAME COMP	1.0 EA	689.20			689.20	S
	REAR FRAME COMP	1.0 EA	689.20			689.20	S
	CLIP NUT	2.0 EA	5.60			11.20	S
	CUSHION, SEAT	1.0 EA	2.50			2.50	S
	PLUG	2.0 EA	2.10			4.20	S
	PLUG, RH	2.0 EA	7.80			15.60	S
	PLUG	2.0 EA	7.80			15.60	S
	REAR WHEEL SPIN	1.0 EA	189.80			189.80	S
	REAR SWINGING A	1.0 EA	2565.00			2565.00	S
	AXLE, REAR SWIN	1.0 EA	160.90			160.90	S
	AXLE, REAR SWIN	1.0 EA	160.90			160.90	S
	BEARING	2.0 EA	33.60			67.20	S
	INNER SPACER	1.0 EA	17.80			17.80	S
	SPACER	1.0 EA	27.60			27.60	S
	SEAL RING	2.0 EA	6.10			12.20	S

92615 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte. Ltd. (DUCATI)
Attn: After Sales/Service

SERVICE ESTIMATE

Inv.No. .. : D 0 Page 2
Inv.date .. : 22/11/2021
WIP No. .. : 55328
Veh. In/Out:
*Tel.No. .. : Work: 63782628
Reg.No. .. : FBS3609B / MTS V4
Reg.date .. : 31/03/2021
Mileage .. : 0
Chassis No.: ZDM1A00AAMB001860
Variant... : MTS V4 S FULL

Closed by : Tony Alfred Desire D
Svc Consultat : 0988
Remarks : Wearnes Automotive P

Op.No	Description	CCC Mech Qty	Price Disc% Pkg	Amount G
	BEARING, NEEDLE	2.0 EA	18.70	37.40 S
	PAD	1.0 EA	6.20	6.20 S
	SCREW, SPECIAL	12.0 EA	1.10	13.20 S
	CHAIN LINK	1.0 EA	42.40	42.40 S

COPY DOCUMENT

Steve (LKK)

8392 8813

23/11/21, 4.30pm

M R
3 dy,
P/P
My Bulky

Labour Total 3,670.00
Parts Total 7,418.50
Package Total 0.00

Amount 11,088.50

Amount 11,088.50
GST @ 7 % 776.20
Total Amount 11,864.70
Less Amt Paid 0.00
Nett Amount 11,864.70

GST: S=StdRated; O=OutOfScope; Z=ZeroRated
Service Estimates are valid for 10 days from the above date.
This is a computer generated invoice, no signature is required.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/11/2021 16:42 (SGT)
Date of Accident 12/11/2021 13:50 (SGT)
Exact Location of Accident Commonwealth Ave, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBS3609B

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Wearnes Automotive Pte Ltd
Company Reg No 1XXXXX400R
Email Address hamdan.misran@wearnes.com
Mobile Phone No (Phone) +65-96708496
Alternative Phone No +65-81261237

VEHICLE PARTICULARS

Manufacturer Ducati
Model Multistrada
Variant Multistrada V4 S Full
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Motorcycle
Transmission Manual
CC 1158

INSURANCE COMPANY

Name of Insurance Company Liberty Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number SD21V00605
Cover Note Number -

DRIVER

Name of Driver SEAH WEI LIE
NRIC No SXXXX879Z

Date Of Birth	28/02/1992
Occupation	Indoor
Date Of Driving Pass	04/06/2021
Driving experience	5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91791653
Alt. Phone Number	-
Email Address	williamseahwt@gmail.com
Address	Block 116 Serangoon North Avenue 1 #09-513
Address complement	-
Postcode	550116
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	TEST DRIVE
Does Driver Own Other Vehicles?	Yes
Vehicle Registration Number of Other Vehicle Owned by Driver	FBS6604U
Insurance Company of Other Vehicle Owned by Driver	Liberty Insurance Pte Ltd

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Motorcyclist
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM8837M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-

Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

1. What is the purpose of the study?

3. *As a result of the investigation, the following was determined:*

4. *What are the implications for the health and equity of people with cardiovascular diseases and diabetes in terms of their ability to access and engage in care to manage their condition?*

5. Any false reporting may be referred to the Police for investigation.

8. In the case of a \mathbb{Z}_2 -homomorphism ϕ from a \mathbb{Z}_2 -module M to a \mathbb{Z}_2 -module N , the kernel of ϕ is a \mathbb{Z}_2 -submodule of M . In the case of a \mathbb{Z}_2 -homomorphism ϕ from a \mathbb{Z}_2 -module M to a \mathbb{Z}_2 -module N , the image of ϕ is a \mathbb{Z}_2 -submodule of N .


© 2004-2005 by the author(s). All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or by any information storage or retrieval system, without permission in writing from the author(s).

$$x, y \in \mathbb{R}^n \setminus \{0\} \implies \frac{1}{\|x\|} \leq \frac{1}{\|y\|} \iff \|x\| \geq \|y\|$$
[illegible][illegible]

Illustration of the test is included
Page 8 of 9

1. 在 1990 年 12 月 31 日，A 公司有一笔应付账款 100 元，在 1991 年 1 月 1 日，A 公司支付了这笔应付账款。

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stopping at traffic light along Lawrenceville Ave.

Just as traffic light turned green, I was about to move off. A car rear-ended me almost but my brakes and stop to check for damage.

Car number plate was involved and the car which rear-ended me had a bad right frontal damage.

After waiting for some time the driver who rear-ended me asked to move to the left lane and to disperse and move. I did not do that and followed me to police station.

Then police and talked about it, and we were told that FRESBY LORIAN HURD.

DECLARATION

I hereby declare that the above information is true and correct to the best of my knowledge.

Signature of Driver
Date: 11/11/2018

Signature of Driver
Date: 11/11/2018

Signature of Driver
Date: 11/11/2018









