

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21011904/REA3Q2**Date:** 19/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SLQ9561G **Insured Vehicle No :** SLN8078H
 Date of Loss: 13/11/2021 Nature of Claim: TP Claim No: MFL2021D0004969

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ9561G**
 Make & Model: HONDA VEZEL HYBRID, 1.5 x (A) Engine No: LEB5951347
 Reg. Date: 27/07/2017 (Man. Year: 2017) Chassis No: RU31251332
 Colour: Black Odometer: 49109 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	872.88	716.72	156.16	17.89
Miscellaneous Items	401.00	401.00	0.00	0.00
Labour	600.00	500.00	100.00	16.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,873.88	1,617.72	256.16	13.67
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	1,873.88	1,300.00	573.88	30.63
+ GST 7.00/7.00% (S\$)	131.17	91.00	40.17	30.62
Nett Amount (S\$)	2,005.05	1,391.00	614.05	30.63
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
Nett Liability (S\$)		1,712.00		

INSPECTION

Date of Assignment: 23/11/2021 Present Location: Mova Automotive Pte Ltd (Bukit Merah)
 Date Inspected: 14/12/2021 Inspected At: Mova Automotive Pte Ltd (Bukit Merah)
 Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
 Singapore 159722
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jun 2022)
Parts:	M1-SUV	HONDA VEZEL HYBRID 1.5 x (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ9561G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	829.40 FL	*829.40 FL
2	1		*REAR BUMPER SIDE LH	Repair	195.20 FL	*- FL
3	1		*REAR BUMPER SIDE BRACKET LH	Cracked	27.50 FL	*27.50 FL
4	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
					Sub Total (\$\$)	1,091.10 895.90
					- List Item Discount on L Items 20.00/20.00% (\$\$)	218.22 179.18
					Total Parts (\$\$)	872.88 716.72

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR BUMPER STEP GARNISH (NECESSARY)	390.00	390.00
2	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			401.00	401.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX DAMAGED PARTS, STRAGHTEN & REALIGN AFFECTED AREAS	New	200.00	200.00
2	TO SPRAY AFFECTED AREAS	New	400.00	300.00
Gross Labour Cost (\$\$)			600.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >