



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System,

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	13/11/2021
Vehicle Reg. No.:	SLQ9561G	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HONDA VEZEL HYBRID, 1.5 X (A)	Vehicle Reg. Date:	27/07/2017
Vehicle Colour:	BLACK	Chassis No:	RU31251332
Engine No:	LEB5951347		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	872.88
Miscellaneous Items	401.00
Labour	600.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	1,873.88
+ GST 7.00% (\$\$)	131.17
Nett Amount (\$\$)	2,005.05

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2021)
Parts: M1-SUV HONDA VEZEL HYBRID 1.5 x (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLQ9561G)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>sun</i>	20.00	0.00	*829.40 FL
2	1		*REAR BUMPER SIDE LH <i>repair</i>	20.00	0.00	*195.20 FL X
3	1		*REAR BUMPER SIDE BRACKET LH <i>?ca</i>	20.00	0.00	*27.50 FL
4	10		*REAR BUMPER CLIPS <i>ca</i>	20.00	0.00	*39.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

1,091.10

- List Item Discount on L Items (S\$)

218.22

Total Parts (S\$)

872.88

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

895.90
208
716.72

Estimates on Miscellaneous Items

Qty	Particulars	Amount
Miscellaneous Items		
1	REAR BUMPER STEP GARNISH <i>ne ✓</i>	390.00
2	OD/TP Case (Insurer) <i>ne ✓</i>	11.00
Sub Total (S\$)		401.00

401

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & REFIX DAMAGED PARTS, STRAGHTEN & REALIGN AFFECTED AREAS	New	200.00
2	TO SPRAY AFFECTED AREAS	New	400.00
Gross Labour Cost (S\$)			600.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Rasul**Hp 90010068**3 days**4s**14/12/21 @ 1030**Resurvey after repair**716.72**401.00**500.00**1617.72**20%**1294.17**4s. \$1,300*