


Not Authorized
Penny Bepain
Jelay



ESTIMATE TO REPAIR

SURVEYOR NAME :	Kenneth (LKK)
DATE OF SURVEY :	04.01.2022
TIME OF SURVEY :	

VEHICLE NO. : SCY 686 D
MAKE : NISSAN
MODEL : SKYLINE 2.5A
YEAR : 1999
CHASSIS NO : ER34018821

DATE : 23-Nov-21
DATE OF ACCIDENT : 13-Nov-21
THIRD PARTY REF : SLE 3481 M / AIG

No.	Parts Description / Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear bumper	Nett		\$ 1,086.60	11
1 pc	Rear bumper reinforcement	Nett		\$ 787.50	11
1 pc	Rear bumper retainer	Nett	\$51.20	\$ 102.40	11
10 ps	rear bumper clip	Nett	\$2.60	\$ 26.00	11
1 pc	rear end panel	Nett		\$ 724.90	11
1 pc	N/s taillamp	Nett		\$ 857.60	11
1 pc	taillamp outer garnish	Nett		\$ 397.60	11
1 pc	taillamp panel	Nett		\$ 285.50	11
1 pc	N/s rear fender	Nett		\$ 1,387.30	11
1 pc	N/s rear fender inner moulding	Nett		\$ 767.10	7
1 pc	rear windscreen moulding	Nett		\$ 183.10	11
					\$6,605.60
	Less 10%				\$660.56
					\$5,945.04
1 tube	Rear windscreen sealant	S.Nett			\$40.00
	To putty and spray paint.				\$1,000.00
	To remove & refix rear windscreen glass.				\$120.00
	To remove & refix rear cushion seat & lining.				\$120.00
	To anti-rust.				\$80.00
	Labour charges.				\$1,500.00
TG-ML/-	TOTAL	Acknowledged by Repairer			\$8,805.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature
Date

Blk 176 Sin Ming Drive #03-03 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd