

6 December 2021

REG NO.: SMC 1755 D ✓
MAKE/MODEL: TOYOTA C-HR ✓

Thuan e Lkhauto.lum
82235969
21/11/21 1300
LIS 4 days up

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear tailgate	\$ 1,258.20 XR
1	Rear tailgate lock	\$ 389.00 XSV
1	Rear tailgate logo	\$ n/c 167.30 88.3
1	Rear tailgate rubber	\$ 300.80 XSR
1	Rear tailgate "C-HR" emblem	\$ n/c 167.30 91.52
1	Rear tailgate "HYBRID" emblem	\$ n/c 129.20
1	Rear taillamp	\$ SCR 738.30 600.2
1	Rear end panel	\$ 988.60 XR
1	Rear end panel inner garnish	\$ 266.60 XSV
1	Rear keyless sensor	\$ 400.70 XSV
1	Rear bumper	\$ DT 823.30
1	Rear bumper centre grille cover	\$ 288.30 XSV
1	Rear bumper lower garnish	\$ SCR 557.70 445 ✓
1	Rear bumper reflector	\$ (ra 120.30
1	Rear bumper reflector garnish	\$ SCR 87.60
1	Rear bumper reinforcement	\$ 385.20 XR
1	Rear bumper side retainer - n/s	\$ n/c 87.70 445 ✓
2	Rear bumper PDC sensors	\$ 570.00 XSV
1	Rear fender wheel arch garnish	\$ C4 188.80 ✓
<div> <p>Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>		
		\$ 7,914.90 ✓
		\$ 1,978.73
		\$ 5,936.18
<u>SPECIAL NETT ITEMS</u>		
1	Rear windscreen inner seal	\$ 85.00 XNN
1	Rear windscreen sealant	\$ 80.00 XNN
1	Rear bumper clip (1 set)	\$ Nec 50.00 20 ✓
		\$ 215.00 ✓
<u>LABOUR CHARGES</u>		
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20 + 10 30
2	To remove and refit inner garnishes.	\$ 150.00 20 + 40 60
3	To remove and refit rear reverse sensor.	\$ 150.00 20 + 30 50
4	To transfer rear tailgate mechanism and wiring assembly.	\$ 120.00 XNN
5	To remove and refit rear windscreen glass.	\$ 180.00 XNN
6	To apply undercoating.	\$ 150.00 30
7	Panel beating.	\$ 1,400.00 600
8	To re-spray painting on the affected areas.	\$ 1,200.00 600 ✓
		\$ 3,430.00

GRAND TOTAL :

\$ 9,581.18

2800