

ASSIGNED BY:

Steve

CS/CT 12101909/E 943

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
To Inspect Vehicle No: _____
or Workshop no: _____
Policy No: _____
Claims No: **SNM21D206726/C02**
Sum Insured: _____
Excuse: _____
Make of Vch: _____
(Policy Condition)
N/S: ☒ O/S: ☒
Det. or Market Value: _____
IOAC Accident Report: _____ Consistent? : Yes or No
DIA / PR Sent: _____ Consistent? : Yes or No
Est. Repair: _____ days Res.: Yes or No
Cum Sum: _____ % 3 Vol.: Yes or No
QA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Vch No: **SNA101X** Yt Regn: **17/3/2021**
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Light / Prime Mover /
Truck / Trailer or
Make: **Aston Martin Vantage** C.B. **3982**
Colour: **Yellow** A/O: Insured / Stolen / N
Sp/Reading: **4126** Yt Regn: Insured / Stolen / N
Eng/No: _____
O/Nr: **SCFSLGAW5KGN02848**
Gen. Cond: Good / Fair / Poor / Bump
Steering: In order / Jammed / Locked / Burnt or
Broken: In order / Jammed / Locked / Burnt or
Mod: M1 / 3/3m / 3/20 A/Rm or
Tyre Size: P1 **255/40ZR20**
R1 _____
BY/DUN/EXNOVA/GY/PS/LIZA/MIC/OHTSV/PIR/SUMI/
TOYO/YOKO or **Pirelli**
Front: **4** mm R/Sel: **4** mm
V/Sel: **4** mm U/Sel: **4** mm
D.O.A. **21/11/21** Wearnies
Survey hold of
Des. of Damages: **Pr** / Rear / O/S / H/S / VIC / Rollup or
The V/S / Chassis frame / Body structure affected due to collision

Date/Time: _____ Action/ Instruction: **MV-640K**
We will be advising our Principal a cost of repair of \$ 41,132.39 (P/P before GST) with 7 days of repair, subject to their approval. (Red \$28304.91, 41%)

Days Of Repair: **7**
Resurvey No. of Trips: **2**
Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Trach. Invo (\$) ☐ VVap/Invo (\$) ☐ Survey Fee ☐ Transportation ☐ S & P S ☐ Fines ☐ Other ☐ Total
22/02 Typist: ☐ Prelim. Report ☐ Final Report
MER-TP
41132.39

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Wealthy Link Pte. Ltd.
 Attn: Mr. Lee Yeow Seng
 38 Beach Road
 #34-11 South Beach Tower
 Singapore 189767

GST Reg.No: M28920628X
 Inv.No. : B&P 0 Page 1
 Inv.date : 24/11/2021
 WIP No. : 56064
 Veh.In/Out:
 *Tel.No. :
 Reg.No. : SNA101X
 Reg.date : 17/03/2021
 Mileage : 0
 Chassis No: SCFSLGAW5KGN02848

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : WEALTHY LINK PTE. LT

| Op.No | Description | Mech | Qty | Price | Disc% | Pkg | Amount | G |
|-------|---|------|-----|----------|-------|------|-----------|----|
| 802 | TO REPLACE BONNET, FRONT BUMPE | 0 | | 8000.00 | 0 | | 8,000.00 | S |
| | RADIATOR GRILLE, FRONT BUMPER 1619 X 4 | | | | | | 6400 | |
| | LOWER SPOILER, HEADLAMP LH/RH, PARKING SENSORS, ETC | | | | | | | |
| 800 | TO SPRAY BONNET, FRONT BUMPER, FRONT SPOILER, ETC 1399 X 2 | 0 | | 5500.00 | 0 | 3900 | 5,500.00 | S |
| 280 | TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES | 0 | | 1020.00 | 0 | | 1,020.00 | /S |
| 280 | TO FOCUS HEADLAMP | 0 | | 340.00 | 0 | | 340.00 | /S |
| R06 | NUMBER PLATE & HOLDER | 0 | | 120.00 | 0 | | 120.00 | S |
| NOTES | HEADLAMP LH/RH - NEED TO BE | 0 | | 0.00 | 0 | | | S |
| CHECK | | | | | | | | |
| | HOOD ASSEMBLY / 00 | 1.0 | EA | 15392.50 | | | 15,392.50 | S |
| | LATCH SECONDARY LH X | 1.0 | EA | 228.50 | | | 228.50 | S |
| | STRKR SECONDARY X | 2.0 | EA | 100.70 | | | 201.40 | S |
| | LATCH SECONDARY RH X | 1.0 | EA | 228.50 | | | 228.50 | S |

Steve (LKK)
 24/11/21, 3:29pm

ML ML
 P/P
 My B/L My
 7 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Wearnes Automotive Pte. Ltd.
 45 Long Kee Road, Singapore 159103 T 6430 4700 www.wearnesc.com

Co reg no: 199501400R / GST reg no. M28920628X
 Date:

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Wealthy Link Pte. Ltd.
 Attn: Mr. Lee Yeow Seng
 38 Beach Road
 #34-11 South Beach Tower
 Singapore 189767

GST Reg.No:M28920628X
 0 Page 2
 Inv.No. . : B&P
 Inv.date. : 24/11/2021
 WIP No. . : 56064
 Veh.In/Out:
 *Tel.No. . :
 Reg.No. . : SNA101X
 Reg.date . : 17/03/2021
 Mileage . : 0
 Chassis No: SCFSLGAW5KGN02848

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : WEALTHY LINK PTE. LT

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|------------------------------------|----------|---------|-------|-----|----------|---|
| | STRIKER- BONNET X | 2.0 EA | 102.10 | | | 204.20 | S |
| | FRT CTR PED LEG FOAM ? | 1.0 EA | 235.20 | | | 235.20 | S |
| | INTAKE FOAM LH UPPER ? | 1.0 EA | 124.70 | | | 124.70 | S |
| | INTAKE FOAM RH UPPER ? | 1.0 EA | 124.70 | | | 124.70 | S |
| | SCRIVET-PACK OF 5 / n/c | 5.0 EA | 2.60 | | | 13.00 | S |
| | FRT BMPR ASSY ROW / CRA | 1.0 EA | 5787.30 | | | 5,787.30 | S |
| | FRONT SPLITTER-BLACK / CUT (Black) | 1.0 EA | 4158.60 | | | 4,158.60 | S |
| | SCR M6 x 14 HD INT / n/c | 9.0 EA | 2.60 | | | 23.40 | S |
| | CLIP SPG M6 PK OF 10 / n/c | 10.0 EA | 2.40 | | | 24.00 | S |
| | WSHR 25mm x 6.4mm-10 / n/c | 2.0 EA | 1.30 | | | 2.60 | S |
| | BOLT M6x35 HEX / n/c | 2.0 EA | 1.90 | | | 3.80 | S |
| | SCREW-M6x20 PACK 20 / n/c | 20.0 EA | 2.70 | | | 54.00 | S |
| | RET GRILLE BMPR(10) / n/c | 10.0 EA | 1.20 | | | 12.00 | S |
| | LAMP ADJUSTER ? | 4.0 EA | 73.00 | | | 292.00 | S |
| | RAD GRILLE BLACK ? | 1.0 EA | 3791.10 | | | 3,791.10 | S |
| | FRONT CAMERA BEZEL / n/c | 1.0 EA | 15.30 | | | 15.30 | S |
| | HLDR CMR FRT FACING / n/c | 1.0 EA | 32.80 | | | 32.80 | S |

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Wealthy Link Pte. Ltd.
 Atn: Mr. Lee Yeow Seng
 38 Beach Road
 #34-11 South Beach Tower
 Singapore 189767

GST Reg.No:M28920628X
 0 Page 3

Inv.No. : B&P
 Inv.date. : 24/11/2021
 WIP No. : 56064
 Veh.In/Out:
 *Tel.No. :
 Reg.No. : SNA101X
 Reg.date : 17/03/2021
 Mileage : 0
 Chassis No: SCFSLGAW5KGN02848

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : WEALTHY LINK PTE. LT

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|----------------------------------|----------|---------|-------|-----|----------|---|
| | IN-GRL PDC HOLDER LH / <i>nc</i> | 1.0 EA | 9.90 | | | 9.90 | S |
| | IN-GRL PDC HOLDER RH / <i>nc</i> | 1.0 EA | 9.90 | | | 9.90 | S |
| | SCRIVET-PACK OF 5 / <i>nc</i> | 20.0 EA | 2.60 | | | 52.00 | S |
| | SENSOR PARKING AID / <i>?</i> | 2.0 EA | 106.40 | | | 212.80 | S |
| | SENSOR PARKING AID / <i>?</i> | 2.0 EA | 106.40 | | | 212.80 | S |
| | SENSOR PARKING AID / <i>x</i> | 2.0 EA | 113.80 | | | 227.60 | S |
| | DECOUPLING RING / <i>?</i> | 6.0 EA | 39.30 | | | 235.80 | S |
| | FRT U/TRAY / <i>?</i> | 1.0 EA | 1098.00 | | | 1,098.00 | S |
| | UTRAY SPPRT BAR / <i>?</i> | 1.0 EA | 1001.10 | | | 1,001.10 | S |
| | CLIP SPG M6 PK OF 10 / <i>nc</i> | 10.0 EA | 2.40 | | | 24.00 | S |
| | SCREW-M6x20 PACK 20 / <i>nc</i> | 20.0 EA | 2.70 | | | 54.00 | S |
| | BADGE ASSY AML / <i>nc</i> | 1.0 EA | 1198.00 | | | 1,198.00 | S |
| | PNL H/LAMP MNT LH / <i>?</i> | 1.0 EA | 2315.20 | | | 2,315.20 | S |
| | PNL H/LMP MNT RH / <i>?</i> | 1.0 EA | 2315.20 | | | 2,315.20 | S |
| | BRKT HD/LP NUT PLT / <i>nc</i> | 2.0 EA | 22.90 | | | 45.80 | S |
| | AUX RAD DUCT RR LH / <i>?</i> | 1.0 EA | 943.10 | | | 943.10 | S |
| | AUX RAD DUCT RR RH / <i>?</i> | 1.0 EA | 943.10 | | | 943.10 | S |

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Wealthy Link Pte. Ltd.
 Atn: Mr. Lee Yeow Seng
 38 Beach Road
 #34-11 South Beach Tower
 Singapore 189767

GST Reg.No:M28920628X
 0 Page 4
 Inv.No. : B&P
 Inv.date. : 24/11/2021
 WIP No. : 56064
 Veh.In/Out:
 *Tel.No. :
 Reg.No. : SNA101X
 Reg.date : 17/03/2021
 Mileage : 0
 Chassis No: SCFSLGAW5KGN02848

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : WEALTHY LINK PTE. LT

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|-----------------------------------|----------|---------|-------|-----|----------|---|
| | BUMPER SEAL / <i>NLC</i> | 2.0 EA | 147.20 | | | 294.40 | S |
| | PNL VNT AIR CTR LWR <i>?</i> | 1.0 EA | 592.70 | | | 592.70 | S |
| | PNL RAD GRL CTR <i>?</i> | 1.0 EA | 1351.50 | | | 1,351.50 | S |
| | SCREW&WSHR M6x20(10) / <i>NLC</i> | 10.0 EA | 1.40 | | | 14.00 | S |
| | PNL VEN AIR CTR UPR <i>?</i> | 1.0 EA | 555.70 | | | 555.70 | S |
| | LWR FRT SPLITTER <i>?</i> | 1.0 EA | 1589.00 | | | 1,589.00 | S |
| | PNL VEN AIR LH <i>?</i> | 1.0 EA | 741.40 | | | 741.40 | S |
| | PNL VEN AIR RH <i>?</i> | 1.0 EA | 741.40 | | | 741.40 | S |
| | RAD SUPPORT LWR <i>?</i> | 1.0 EA | 946.10 | | | 946.10 | S |

Labour Total 14,980.00
 Parts Total 48,674.10
 Package Total 0.00

Gross Total. 63,654.10
 Net..... 63,654.10
 GST @ 7.0% 4,455.79
 Total..... 68,109.90
 Paid..... 0.00
 Please Pay.. 68,109.90

GST: S=StdRated; O=OutOfScope; Z=ZeroRated