

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 25 Nov 2021

Preliminary Advice

Insured : SMQ3530Z

Vehicle No

TP Vehicle : GBG3196M
No

Accident Date : 18/11/2021

Make : TOYOTA HIACE

Assignment Date : 23/11/2021

Date of : 24/11/2021

Est. Duration of : 4
Repair

Inspection

Inspection At : LIU'S BROTHER AUTO ENGINEERING WORKSHOP (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT
SINGAPORE 417883

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 6,275.00

Revised Amount :S\$ 4,159.90

Check Items (Estimated) :S\$ 262.30

Total :S\$ 4,422.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate :S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.