



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

KIA
Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Chou Kin Sang (zhao Qingsheng)	Cust No/Name /Chou Kin Sang (ZHAO QINGSHENG)
BLK 43 JALAN TIGA #12-20 SINGAPORE 390043	Reg No/Reg Date SLW1792C / 31/01/201
Contact No Mobile: 92383178	Date In/Mileage / 0
	Chassis No KNAFX411MJ5761496
	Engine No G4FGHH691458
	Make/Model KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	23/11/2021/ 15:39	TLC	442 / CocoLu	42801
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW REAR BUMPER, REPAIR BOOTLID			400	800.00
E PNT98000	SPRAY PAINT FOR REAR BUMPER, BOOTLID			350	700.00
E PNT88000	REMOVE & INSTALL PARKING SENSOR				60.00
A 90000001	CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY	C&C LOGO				X 40.00
M SUNDRY	Sundry				20.00
M COVER-RR BUMPER		1.00	688.00	00.00	550.40 688.00
M COVER-RR BUMPER,CTR		1.00	315.00	00.00	252.00 315.00
M BEAM-RR BUMPER		1.00	318.00	00.00	254.40 318.00
M STAY-RR BUMPER RH		1.00	120.00	00.00	120.00
M STAY-RR BUMPER LH		1.00	120.00	00.00	96.00 120.00
M BRACKET-RR BEAM UPR MTG		1.00	3.00	00.00	3.00
M BRACKET-RR BEAM UPR MTG,RH		1.00	3.00	00.00	3.00
M BRACKET-RR BUMPER SIDE MTG,LH		1.00	33.00	00.00	33.00
M BRACKET-RR BUMPER SIDE MTG,RH		1.00	29.00	00.00	29.00
M LOGO ASSY-KIA SUB		1.00	37.00	00.00	37.00
M EMBLEM-CERATO		1.00	35.00	00.00	35.00
M TRIM-TRANSVERSE RR		1.00	58.00	00.00	58.00
Estimate LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No legal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company • Third party survey is on a "Without Prejudice" basis Acknowledged by Repairer Signature: _____ Authorized signatory and company stamp					
Steve (LKK) MR PL 29/11/21, 11:44am P/P My Bol 3 days					
Confirm & accept 7% GST on					
Net 3,529.00 3529.00					3,529.00 247.03
Total Payable					3,776.03

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SLW 1792 C**

	<u>Labour</u>	<u>Cost (\$)</u>
1	Supply one set of reverse sensor	220.00 — BR
	Total Labour	220.00
	Taxable amount	220.00
	7% GST	15.40
	Grand total	<u>\$ 235.40</u>

Thank You.

Yours faithfully

A blue ink signature, appearing to read "Loi Ai Ting", written over the "Yours faithfully" text.

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240