



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT21003606	Page	1
Registration No	: SKZ4724B	Date	: 23. Nov 2021	Customer No.	: WZC008
Chassis No	: JHMRC1890GC201450	Svc Advisor	: ANIKKA LAI SWEE KAM	Engine No	: K24W72010617
Model	: ODYSSEY 2.4 EXV-S 16YM	Date Time	: 23. Nov 2021 11:51:07 AM	Surveyor Name	:
Owner's Name	: LEE WAI KONG	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 22/11/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LEE WAI KONG OWNER INSURER: LIBERTY ACC DATE: 22/11/2021 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH : GBC2035Y							
67550-T6A-J00ZZ	PANEL COMPL.SLIDE DOOR	1	1067.00	25	800.25	56.02	856.27	
67861-T6A-305ZA	TAPE SETL.RR.DOOR SASH INNER	1	60.90	25	45.67	3.20	48.87	
72950-T6A-003	MOLDING ASSYL.RR.DOOR	1	74.20	25	55.65	3.90	59.55	
75333-T6A-J11ZB	GARNISH ASSYL.SLIDE DOOR LWR	1	290.10	25	217.57	15.23	232.80	
74591-T6A-000	FENDERL.RR INNER	1	124.00	25	93.00	6.51	99.51	
04646-T6A-J22ZZ	PANEL SET,L.RR.OUTER	1	997.30	25	747.97	52.36	800.33	
72955-T6A-003	MOLDING ASSYL.QTR WINDSHIELD	1	117.00	25	87.75	6.14	93.89	
72585-T6A-000ZZ	COVER COMPL.SLIDE DR CTR RAIL	1	175.50	25	131.62	9.21	140.83	
71507-T6A-003ZB	FACE,L.RR.BUMPER GARNISH	1	81.90	25	61.42	4.30	65.72	
04715-T6A-900ZZ	FACERR.BUMPER	1	606.10	25	454.57	31.82	486.39	
71502-T6A-003ZB	FACER.RR.BUMPER GARNISH	1	81.90	25	61.42	4.30	65.72	
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	20.40	25	15.30	1.07	16.37	
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	20.40	25	15.30	1.07	16.37	
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46	
42700-T6A-J81	DISK ALUMINIUM WHEEL 17X7J	1	975.70	25	731.77	51.22	782.99	
					Sum Item	3536.51	247.56	3,784.07
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00	
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60	

Printed on 23/11/2021 12:10:11 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT21003606	Page	2
Registration No	: SKZ4724B	Date	: 23. Nov 2021	Customer No.	: WZC008
Chassis No	: JHMRC1890GC201450	Svc Advisor	: ANIKKA LAI SWEE KAM	Engine No	: K24W72010617
Model	: ODYSSEY 2.4 EXV-S 16YM	Date Time	: 23. Nov 2021 11:51:07 AM	Surveyor Name	:
Owner's Name	: LEE WAI KONG	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 22/11/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BKDR31R	REMOVE & TRANSFER ITEMS TO NEW RR L SLIDING DR.	1	650.00		650.00	45.50	695.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	31.50	481.50
BC01R	PERFORM SETTING ON MULTI VIEW CAMERAS & SMART	1	450.00		450.00	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	45.50	695.50
BG31R	REPLACE RR. L DOOR QTR GLASS.(N)	1	650.00		650.00	45.50	695.50
BOJSE	BODY JOINT SEALANT QTR GLASS	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT LHR FENDER	1	100.00		100.00	7.00	107.00
BKFE21R	CUT & RENEW RR L FENDER. STRAIGHTEN INNER PANEL	1	3500.00		3500.00	245.00	3745.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	3000.00		3000.00	210.00	3210.00
Sum Labor					10010.00	700.70	10,710.70
BO-WHEEL ALIGN X4 WHEEL ALIGNMENT X4		1	180.00		180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

Survey By _____

Date & Time _____

Excess _____

Status _____

Signature _____

Total Amount 13,726.51 960.86 14,687.37

Total (Inclusive of GST) 14,687.37

Printed on 23/11/2021 12:10:11 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.