

JA AUTOCARE PTE LTD

160 Sin Mign Dr
 #08-16 Sin Ming AutoCity
 Singapore 575722
 Tel : 94513429

*Not Not hatched
 1/1 Sy @ 2400hr
 Putty After Pain
 4 days*

-1

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Motor Claims Department

Date : 23.11.2021
 Vehicle No. : GBF 1457D
 Make/Model : NISSAN NV200
 Chassis/Eng# :
 Accident Date : 19.11.2021

01) Rear rh door	<i>1093.90</i>	\$	<i>Bu</i>	1,350.00	<i>—</i>
02) Rear rh door hinge		\$	<i>pu</i>	65.00	<i>—</i>
03) Rear bumper		\$	<i>Bu</i>	650.00	<i>—</i>
04) Rear bumper bracket rh		\$	<i>pu</i>	65.00	<i>x</i>
05) Rear bumper retainer rh		\$	<i>dit</i>	50.00	<i>—</i>
06) Rear bumper reinforcement		\$	<i>pu</i>	450.00	<i>x</i>
07) Rear bumper clips		\$	<i>pu</i>	60.00	<i>—</i>
08) Rear fender rh		\$	<i>pu</i>	950.00	<i>x</i>
		<i>10%</i> \$		3,640.00	
		<i>-30%</i> \$		(1,092.00)	
		\$		2,548.00	
Nett Items					
09) Tail lamp assy	<i>289.50</i>	\$	<i>CAH</i>	550.00	<i>—</i>
10) dc emblem		\$	<i>pu</i>	50.00	<i>—</i>
		\$		600.00	
		Less 10%		(60.00)	
		\$		540.00	
11) Reverse sensor (s/Nett)		\$	<i>pu</i>	280.00	<i>x</i>
12) rear windscreen sealant & clips (s/Nett)		\$	<i>pu</i>	60.00	<i>40sm</i>
		\$		340.00	
Labour Charges					
13) To check wiring		\$		120.00	<i>2dl</i>
14) To dismantle & refix rear rh windscreen glass		\$		100.00	<i>5dl</i>
15) To knock out dents on affected areas & renew parts		\$		800.00	<i>500l</i>
16) To putty & respray painting		\$		1,200.00	<i>40dl</i>
		\$		2,220.00	
		\$		5,648.00	

for JA AUTOCARE PTE LTD

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: