

**JA AUTOCARE PTE LTD**

160 Sin Mign Dr  
 #08-16 Sin Ming AutoCity  
 Singapore 575722  
 Tel : 94513429

*Not Not have  
 L/Sy &  
 Recovery After Pain  
 4 days*

-1

**ESTIMATE**

AIG Asia Pacific Insurance Pte Ltd  
 78 Shenton Way  
 #07-16 AIG Building  
 Singapore 079120  
 Attn: Motor Claims Department

Date : 23.11.2021  
 Vehicle No. : GBF 1457D  
 Make/Model : NISSAN NV200  
 Chassis/Eng# :  
 Accident Date : 19.11.2021

- 01) Rear rh door
- 02) Rear rh door hinge
- 03) Rear bumper
- 04) Rear bumper bracket rh
- 05) Rear bumper retainer rh
- 06) Rear bumper reinforcement
- 07) Rear bumper clips
- 08) Rear fender rh

\$	<i>By</i>	1,350.00	—
\$	<i>rh</i>	65.00	—
\$	<i>Bu</i>	650.00	—
\$	<i>rh</i>	65.00	x
\$	<i>dit</i>	50.00	—
\$	<i>r</i>	450.00	x
\$	<i>rh</i>	60.00	—
\$	<i>r</i>	950.00	x
<i>10%</i>	\$	3,640.00	
<i>-30%</i>	\$	(1,092.00)	
\$		<u>2,548.00</u>	

**Nett Items**

- 09) Tail lamp assy
- 10) dci emblem

<i>10%</i>	\$	<i>CAH</i>	550.00	—
	\$	<i>rh</i>	50.00	—
	\$		600.00	
Less 10%	\$		(60.00)	
	\$		<u>540.00</u>	

- 11) Reverse sensor (s/Nett)
- 12) rear windscreen sealant & clips (s/Nett)

\$	<i>rh</i>	280.00	x
\$	<i>rh</i>	60.00	<i>40sm</i>
\$		<u>340.00</u>	

**Labour Charges**

- 13) To check wiring
- 14) To dismantle & refix rear rh windscreen glass
- 15) To knock out dents on affected areas & renew parts
- 16) To putty & respray painting

\$		120.00	<i>2ol</i>
\$		100.00	<i>5ol</i>
\$		800.00	<i>5ool</i>
\$		1,200.00	<i>4ool</i>
\$		<u>2,220.00</u>	

for JA AUTOCARE PTE LTD

**LKK Auto Consultants** hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

\$ 5,648.00