

SLX69749, 2008 April

Honda Freed 1496cc

GB71060158

TP ALG.

Leilia

Rear Bumper Deband 828.90 ✓

Rear Bumper Clips. <sup>new</sup> 30 (SN) ✓

Rear Bumper Side Holder RH <sup>new</sup> 49.80 ✓

Taillamp RH. <sup>new</sup> 629.10 ✓

Rear RH Fender Distorted 912.40 ✓

Rear RH Fender Inner Shield <sup>new</sup> 140.20 X

Rear RH Fender Inner Shield Clips <sup>new</sup> 30 (SN) X

Rear RH Fender Inner Trim Board <sup>new</sup> 586.40 X

Rear RH Fender Inner Trim Board Clips <sup>new</sup> 30 (SN) X

Rear RH Fender Top Cover <sup>new</sup> 398.90 X

Rear RH Fender Glass Sealant <sup>new</sup> 40 (SN) ✓

Rear RH Fender Air Grille <sup>new</sup> 40.50 ✓

Sliding Door RH .. Distorted 1153.40 ✓

Sliding Door Weatherstripe RH. 185.40 X  
<sup>new</sup>

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey, on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLX 69746

Siding Door Lock RH. NLM	262.40	X
Rear RH Wheel Rim. Best	<del>300(SN)</del> / 150(SN)	
Rear RH Wheel Rim Cover	<del>150(SN)</del> 100(SN)	
Rear RH Tyre NLM	250(SN)	X
Rear Axle NLM	1450.90	X
Rear RH Wheel Hub c/w Bearing Dwyd	326.80	✓
Rear RH Shock Absorber. NLM	289.40	X
	3940.90 S.N: 320	
	315272	
Panel Beeding	<del>1200</del> 800	
Spray Painting	<del>1200</del> 600	
Wiring,	1870 <del>50</del> 30	
To spray tuff coat	<del>150</del> 80	
To remove reverse sensor	<del>100</del> 30	(4.2K)
To remove upholstery.	<del>150</del> 80	
To remove fender g/s)	<del>100</del> 50	4/s 4.2K
To remove rear undercarriage	<del>380</del> 100	06 Days
To perform wheel alignment.	<del>150</del> 80	