

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG121011927/TQF3E2

Date: 02/03/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: DMCG21004886
Claimant Vehicle No : FBS8821X Insured Vehicle No : XE676P
Date of Loss: 15/11/2021 Nature of Claim: TP Claim No: CDMCG21002213

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBS8821X**
Make & Model: KAWASAKI BX125A, 125cc Engine No: BX125AEP12216
Reg. Date: 25/08/2021 (Man. Year: 2019) Chassis No: MH4BX125AAJP04501
Colour: Green Odometer: 0 km
Engine Capacity: 125 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80 R17 Rear Tyre Size: 130/70 R17
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,390.00	2,151.00	239.00	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	450.00	330.00	42.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,170.00	2,601.00	569.00	17.95

INSPECTION

Date of Assignment: 24/11/2021
Date Inspected: 24/11/2021 Inspected At: Pang Scooter Service (HQ)
BLK 1006 BUKIT MERAH LANE 2 #01-06
Singapore 159762
Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Mar 2022)	
Parts:	N/A	KAWASAKI BX125A 125cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS8821X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FOOTREST ASSY	Cut	85.00 F	*85.00 FL
2	1		*R/H FOOTREST BRACKET	Broken	135.00 F	*135.00 FL
3	1		*MUFFLER ASSY	Bent	695.00 F	*695.00 FL
4	1		*MUFFLER GUARD	Bent	120.00 F	*120.00 FL
5	1		*BRAKE PEDAL	Bent	68.00 F	*68.00 FL
6	1		*MUFFLER JOINT GASKET	Necessary	38.00 F	*38.00 FL
7	1		*R/H HANDLER BAR	Bent	165.00 F	*165.00 FL
8	1		*R/H HANDLER END	Cut	38.00 F	*38.00 FL
9	1		*R/H REAR FOOTREST	Bent	68.00 F	*68.00 FL
10	1		*R/H REAR FOOTREST BRACKET	Bent	98.00 F	*98.00 FL
11	1		*R/H MIRROR	Cut	110.00 F	*110.00 FL
12	1		*MIRROR BRACKET	Bent	185.00 F	*185.00 FL
13	1		*BRAKE LEVER	Bent	35.00 F	*35.00 FL
14	1		*FRONT BRAKE DISC	Bent	210.00 F	*210.00 FL
15	1		*UNDLER BRACKET	Bent	210.00 F	*210.00 FL
16	1		*STEERING CON	Bent	130.00 F	*130.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,390.00	2,390.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	239.00
Total Parts (S\$)	2,390.00	2,151.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FORK ALIGNMENT	New	200.00	120.00
2	TRANSPORT	New	80.00	80.00
3	LABOUR	New	500.00	250.00
Gross Labour Cost (\$)			780.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >