

ASS. REC. BY:

REF:

CS/EG121011927/T1483

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBS 8821XYr Regn: 3 / 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Kawasaki

C.C. _____

Colour: Green

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl: NI / S/Rim / STD A/Rim or _____Tyre Size: F: 100/80R17R: 130/70R17BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 5 mmR/Bal. 5 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. _____

D.O.I. 24/6/21Survey held at Pay ScooterDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Rep. Formed: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: FBS 8821X

DOA : 15/11/2021

MAKE/MODEL : KAWASAKI BX125

S/No	DESCRIPTION	AMOUNT
1	FRONT FOOTREST ASSY	\$85.00 cut ✓
2	R/H FOOTREST BRACKET	\$135.00 kn ✓
3	MUFFLER ASSY	\$695.00 bc ✓
4	MUFFLER GUARD	\$120.00 bb ✓
5	BRAKE PEDAL	\$68.00 bt ✓
6	MUFFLER JOINT GASKET	\$38.00 re ✓
7	R/H HANDLER BAR	\$165.00 bt ✓
8	R/H HANDLER END	\$38.00 at ✓
9	R/H REAR FOOTREST	\$68.00 bt ✓
10	R/H REAR FOOTREST BRACKET	\$98.00 bt ✓
11	R/H MIRROR	\$110.00 at ✓
12	MIRROR BRACKET	\$185.00 bt ✓
13	BRAKE LEVER	\$35.00 bc ✓
14	FRONT BRAKE DISC	\$210.00 bt ✓
15	UNDLER BRACKET	\$210.00 x
16	STEERING CON	\$130.00 x
17	FORK ALIGNMENT	\$200.00 120
18	TRANSPORT	\$80.00 ✓
19	LABOUR	\$500.00 250
	Tanaka 97495749	2050
	Wt 24/11/21 @ 430pm 10% - 1845	
	plz bring new parts	450
	Tanaka p 1/11/2021	\$2295
	4 days	04 days #
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		
Total :		\$3,170.00

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618

Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: FBS 8821X

DOA : 15/11/2021

MAKE/MODEL : KAWASAKI BX125

S/No	DESCRIPTION	AMOUNT
1	FRONT FOOTREST ASSY	\$85.00 cut ✓
2	R/H FOOTREST BRACKET	\$135.00 h ✓
3	MUFFLER ASSY	\$695.00 bc ✓
4	MUFFLER GUARD	\$120.00 bc ✓
5	BRAKE PEDAL	\$68.00 bt ✓
6	MUFFLER JOINT GASKET	\$38.00 h ✓
7	R/H HANDLER BAR	\$165.00 bt ✓
8	R/H HANDLER END	\$38.00 wt ✓
9	R/H REAR FOOTREST	\$68.00 bt ✓
10	R/H REAR FOOTREST BRACKET	\$98.00 bt ✓
11	R/H MIRROR	\$110.00 wt ✓
12	MIRROR BRACKET	\$185.00 h ✓
13	BRAKE LEVER	\$35.00 bc ✓
14	FRONT BRAKE DISC	\$210.00 bt ✓
15	UNDLER BRACKET	\$210.00 bt ✓
16	STEERING CON	\$130.00 bt ✓
17	FORK ALIGNMENT	\$200.00 120
18	TRANSPORT	\$80.00 ✓
19	LABOUR	\$500.00 250
	Tanpin 9749549	2390
	wt 24/11/21 @ 430pm 10%	2151
	ply using new parts	450
	Tanpin @ 11h afternoon	\$2601
	4 days	04 days #
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____		