

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLN1245M
Accident Date : 21-Nov-2021

No. : 06489

Date : 22-Nov-2021

Our Ref : 021172 (AUTO & GEN) / SHIJIE

PAGE : 1

LIU HONGWEI
11 SERANGOON AVE 2
#11-33
Singapore 556135

Not Authorized
LIU Hongwei
Money After Pain
6 days

ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS SKR4343J

1 pc Rear bumper		520.56	—
1 pc Rear bumper retainer LH		111.24	—
1 pc Rear bumper retainer RH		111.24	—
2 pcs Rear bumper reflector		126.80	X
2 pcs Parking sensors		500.00	200.00
1 pc Rear bumper reinforcement	short @ S\$ 63.40	413.32	—
1 pc Rear end panel	590	628.24	—
1 pc End panel top garnish		247.97	—
1 pc Bootlid striker lock cover		63.18	—
1 pc Antenna sensor		187.60	—
1 pc Spare tyre floor panel		849.85	X
1 pc Spare tyre floor board		274.32	—
1 pc Bootlid		707.40	—
1 pc Bootlid chrome moulding		250.02	—
1 pc Bootlid hinge LH		72.25	X
1 pc Bootlid hinge RH		72.25	X
1 pc Bootlid reflector LH		358.45	—
1 pc Bootlid reflector RH		358.45	—
1 pc Toyota logo		62.96	—
1 pc "COROLLA" emblem		43.20	—
1 pc "ALTIS" emblem		48.92	—
1 pc Bootlid inner trim		373.46	X
1 pc Bootlid lock	371.75	409.54	—
1 pc Bootlid locker striker		19.44	X
1 pc Bootlid weatherstrip		179.71	50.00
2 pcs Tail lamp		846.50	—
2 pcs Tail lamp gasket		56.16	—
2 pcs Tail lamp panel		259.20	X
Rea exhaust pipe		8,152.23	—
		2,038.06	—
		6,114.17	—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLN1245M

Page : 2

1 pc Rear number plate with casing

Per 60.00 *sn* X

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700
1,200.00

To putty and spray replaced parts

1,000.00 *800*

To apply undersealing

60.00 ✓

To remove trims and boards

50.00 ✓

To remove and renew parking sensors

50.00 ✓

To rewire damaged parts

60.00 *200*

Total : S\$ 8,594.17

9,368.25

Singapore Dollars Eight Thousand Five Hundred
and Ninety Four and Cents Seventeen Only