



ALG - OD (REVERT)
SURVEY: 01/12/21
LHK - STEVE

VEHICLE NO : SNB 2914Z

MODEL : MIT/OUTLANDER 2.0 CVT

WIP : 17844

Material	:	\$	<u>1,822.56</u>
Labour	:	\$	<u>2,025.00</u>
Sub-Total	:	\$	<u>3,847.56</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>3,847.56</u>
GST 7%	:	\$	<u>269.33</u>
Grand Total	:	\$	<u>4,116.89</u>
Finalise By/Date : <u>Urry on 16/12/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (wk end)

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 01/12/2021	Cust No/Name	/XIAO XIAO
	Reg No/Reg Date	SNB2914Z / 12/08/2021
	Date In/Mileage	08/12/2021/ 3885
	Chassis/Package	GF7W0701261 /FS5P
	Engine No	4J11DC2875
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	16/12/2021/ 16:44	BLK	884 / Lauro Songcuan	17844
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, TAILGATE & AFFECTED AREAS					675.00 ✓
E PNT98000 SPRAY PAINT ON REAR BUMPER & TAILGATE					700.00 ✓
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR					240.00 ✓
M SUNDRY APPLY WINDSCREEN SEALANT					80.00 ✓
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST					80.00 ✓
M SUNDRY APPLY SEALANT ON AFFECTED AREAS					40.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					120.00 ✓
M SUNDRY SUPPLY C&C EMBLEM					40.00 ✓
M SUNDRY SUNDRIES					20.00 ✓
X FACE,RR BUMPER ✓		1.00	811.00	23.00	624.47 ✓
X EXTENSION,RR BUMPER ✓		1.00	289.00	23.00	222.53 ✓
X CLIP,RR BUMPER ✓		1.00	6.00	23.00	4.62 ✓
X PANEL ASSY, TAILGATE ✓		1.00	989.00	23.00	761.53 ✓
X STOPPER,WINDSHIELD GLASS ✓		2.00	3.00	23.00	4.62 ✓
X DAM, TAILGATE, LWR ✓		1.00	41.00	23.00	31.57 ✓
X DAM, TAILGATE SIDE ✓		2.00	27.00	23.00	41.58 ✓
X FASTENER, WINDSHIELD ✓		4.00	6.00	23.00	18.48 ✓
X DAM, TAILGATE, UPR ✓		1.00	13.00	23.00	10.01 ✓
X MARK, OUTLANDER ✗		1.00	95.00	23.00	73.15 ?
X EMBLEM MIVEC TECHNOLOGY ✓		1.00	30.00	00.00	30.00 ✓
Z TEXT AIG OD CLAIM - REVERT					



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



THIS IS NOT AN OFFICIAL TAX INVOICE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No .6419 1892 01/12/2021	Cust No/Name	/XIAO XIAO
	Reg No/Reg Date	SNB2914Z / 12/08/2021
	Date In/Mileage	08/12/2021/ 3885
	Chassis/Package	GF7W0701261 /FS5P
	Engine No	4J11DC2875
	Make/Model	MIT/ZOMY OUTLANDER 2.0 CVT MODERN (997)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	16/12/2021/ 16:44	BLK	884 / Lauro Songcuan	17844

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
DOA: 22/11/2021 SURVEY: STEVE (LKK) 01/12/2021 05 DAYS				
Pro Forma				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	1,822.56		Nett	3,847.56
Labour	1,845.00	7% GST on	3847.56	269.33
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00		Total Payable	4,116.89
Sundry/Others	180.00			
Total(w/o GST)	3,847.56			

This is not an official tax invoice.
This is a computer generated document, no signature is required.

CAR NO: SN/B 29142WIP: 17844 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Mark Outlander	? / SUPP			Star 6/12/21
2		? / SUPP			
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	8/12	
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: OutlanderSURVEYOR: Steve-Lille

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW21091-00
V.C.I. Version	B179
Vehicle Information	DBA-GF7W XTX 2020MY

Reg No: SNB2914Z

Before to use MUT-3 Not unit to check,
all the board

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
OSS	OSS_9588000B		No DTCS		
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSCFM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
EPB	EPB_4C080000	C2253	EPB SW malfunction	Stored	
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW21091-00
V.C.I. Version	B179
Vehicle Information	DBA-GF7W 2020MY

Reg No: 3NB2914Z

Order to using MOT3 NG unit to ECU

is ECU good

as Job Done by GAC Test drive.

2021.12.08

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
OSS	OSS_9588000B		No DTCS		
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
EPB	EPB_4C080000		No DTCS		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A 0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0 080000		Non-equipped System or Communication Error		