



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/XIAO XIAO
	Reg No/Reg Date	SNB2914Z / 12/08/202
	Date In/Mileage	/ 0
	Chassis No	GF7W0701261
	Engine No	4J11DC2875
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No					
KAX00008	Credit	23/11/2021/ 16:57	BLK	282 / Kevin Leong	17844					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount		
E	PNT88000	REPLACE REAR BUMPER, TAILGATE & AFFECTED AREA REPAIR ON END PANEL								1800.00
E	PNT98000	PAINT WORK ON REAR BUMPER & TAILGATE								700.00
E	PNT88000	REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR								240.00
M	SUNDRY	TO APPLY WINDSCREEN SEALANT								80.00
E	PNT88000	REMOVE & INSTALL REAR PARKING ASSIST								80.00
E	PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								120.00
M	SUNDRY	TO APPLY SEALANT ON AFFECTED AREA								80.00
M	SUNDRY	PERFORM RUST PREVENTION								40.00
A	54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A	10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								120.00
M	SUNDRY	TO SUPPLY C & C EMBLEM								40.00
M	SUNDRY	SUNDRIES								50.00
M	REINFORCEMENT,RR BUMPER,LH			1.00	79.00	23.00		60.83		
M	REINFORCEMENT,RR BUMPER,RH			1.00	79.00	23.00		60.83		
M	BRKT,R/BMPR FACE SIDE,RH			1.00	12.00	23.00		9.24		
M	BRKT,R/BMPR FACE SIDE,LH			1.00	12.00	23.00		9.24		
M	FACE,RR BUMPER			1.00	811.00	23.00		624.47		
M	EXTENSION,RR BUMPER			1.00	289.00	23.00		222.53		
M	CLIP,ENG ROOM COVER			2.00	2.00	23.00		3.08		
M	CLIP,ENG ROOM COVER			2.00	2.00	23.00		3.08		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/XIAO XIAO
	Reg No/Reg Date	SNB2914Z / 12/08/202
	Date In/Mileage	/ 0
	Chassis No	GF7W0701261
	Engine No	4J11DC2875
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	23/11/2021/ 16:57	BLK	282 / Kevin Leong	17844		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	CLIP,RR BUMPER			1.00	6.00	23.00	4.62
M	W/STRIP,TAILGATE OPENING			1.00	213.00	23.00	164.01
M	PANEL ASSY,TAILGATE			1.00	989.00	23.00	761.53
M	GARNISH,TAILGATE			1.00	496.00	23.00	381.92
M	STOPPER,WINDSHIELD GLASS			2.00	3.00	23.00	4.62
M	DAM,TAILGATE,LWR			1.00	41.00	23.00	31.57
M	DAM,TAILGATE SIDE			2.00	27.00	23.00	41.58
M	FASTENER,WINDSHIELD			4.00	6.00	23.00	18.48
M	DAM,TAILGATE,UPR			1.00	13.00	23.00	10.01
M	GLASS,TAILGATE WINDOW			1.00	657.00	23.00	505.89
M	MARK,OUTLANDER			1.00	95.00	23.00	73.15
M	EMBLEM MIVEC TECHNOLOGY			1.00	30.00	00.00	30.00

Confirm & accepted by

7% GST on **Nett** **6,400.68**
 448.05
Total Payable **6,848.73**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.