

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0945/2021/JT
DATE : 22-Nov-21
WIP : 54902

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/11/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

3 days - ok - Jy - 16 Dec 21

OWNER'S NAME : MR SEBASTIAN JOSE ALUKKAL
ADDRESS : 90 EDGEDALE PLAINS
#12-23 THE TERRACE
SINGAPORE 828685
TELEPHONE : HP +65 96455566
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070175559
VEHICLE NO : **SMW 9546 H**
MODEL CODE : AUDI Q3 SB 1.4 TFSI S
MODEL YEAR : 18/12/2020
ENGINE NO : CZD C15468
CHASSIS NO : WAUZZZF30M1040028
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Nov-21
PLACE OF ACCIDENT : TEKKA MARKET (CARPARK)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 9546 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER MODULE DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	\$ 280.00
2	TO INSTALL SOLAR FILM FOR RHS FRONT DOOR WINDOW GLASS.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW RHS FRONT DOOR. TO REPAIR RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$ 500.00
4	TO RESPRAY RHS FRONT DOOR, DOOR COVER, RHS ROOF CHANNEL AND RHS REAR DOOR. (Additional \$150 for respray door cover)	\$	3,500.00	\$ 700.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	6,092.00	\$ 1,672.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 9546 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH	1	\$ 2,816.00	\$ 2,252.80
2	FRONT DOOR OUTER SEAL - RH	1	\$ 116.00	\$ 132.80
3	FRONT DOOR CATCH - RH	1	\$ 120.00	
4	FRONT WINDOW GUIDE TRIM - RH	1	\$ 257.00	\$ 205.20
5	FRONT DOOR B-PILLAR TRIM - RH	1	\$ 112.00	\$ 89.20
6	FRONT WINDOW ALUMINIUM SLOT SEAL TRIM - RH OUTER	1	\$ 224.00	
7	FRONT DOOR WINDOW GUIDE - RH	1	\$ 433.00	\$ 346.40
8	TYRE PRESSURE DATA PLATE	1	\$ 30.00	\$ 24.00
9	FRONT DOOR WINDOW - RH	1	\$ 242.00	
10	REAR DOOR B-PILLAR TRIM RH	1	\$ 117.00	
11	REAR WINDOW GUIDE TRIM - RH	1	\$ 152.00	
12	REAR WINDOW ALUMINIUM SLOT SEAL TRIM - RH OUTER	1	\$ 273.00	
13	FRONT DOOR LOWER COVER - RH	1	\$ 370.00	\$ 296.00
14	SUNDRIES	S/N	\$ 300.00	
TOTAL SPARE PARTS		:	\$ 5,562.00	\$ 3,346.40
TOTAL LABOUR CHARGES		:	\$ 6,092.00	\$ 1,672.00
GRAND TOTAL		:	\$ 11,654.00	\$ 5,018.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT