

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 29 Dec 2021

## **Preliminary Advice**

Insured : GBD4150D

Vehicle No

TP Vehicle : GBK8051T  
No

Accident Date : 18/11/2021

Make : TOYOTA DYNA 150

Assignment Date : 25/11/2021

Date of : 27/12/2021

Est. Duration of : 8

Inspection

Repair

Inspection At : EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD (HQ)  
56 LOYANG WAY #06-07, LOYANG ENTERPRISE BUILDING  
SINGAPORE 508775

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 18,705.28

Revised Amount :S\$ 4,264.65

Check Items (Estimated) :S\$ 2,900.00

Total :S\$ 7,164.65

Lump Sum Repair :S\$

## **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate :S\$

|                   |      |
|-------------------|------|
| Salvage Value     | :S\$ |
| Margin for Repair | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.