

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PC216SP. 2013 Dec.

TP A16.

Xiao Chun.

Mitsubishi Rosa 4899cc

BE63DJF10143.

|                             |                  |            |     |
|-----------------------------|------------------|------------|-----|
| Rear Number Plate           | Bent             | 30(SN)     | ✓   |
| Rear Number Plate Holder    | dehd             | 30(SN)     | ✓   |
| Rear Number Plate Lamp x02  | <sup>14</sup> mm | 68x2=136.  | +   |
| Rear Bumper.                | Distorted        | 1652       | ✓   |
| Rear Bumper Side Holder x02 | mm               | 110x2=220. | ✓   |
| Rear Bumper Lamp x02        | LH cracked       | 154x2=308  | ✓   |
| Rear End Panel              | Distorted        | 899.       | ✓   |
| Rear End Panel Inner Frame. | Distorted        | 980.       | ✓   |
| Taillamp x 02.              | LH could         | 290x2=580  | 290 |
| Taillamp Panel LH.          | Distorted        | 985        | ✓   |
| Rear LH Door.               | Distorted        | 3565       | ✓   |
| Rear LH Door Lock           | Joined           | 345        | ✓   |
| Rear LH Door Weatherstripe. | mm               | 256.       | ✓   |

PC2165P.

|                                     |             |                           |   |
|-------------------------------------|-------------|---------------------------|---|
| Reer LH Door Hinge x02              | But         | 102x2=204.                | ✓ |
| Reer LH Door Outer Handle.          | Pyd         | 195                       | ✓ |
| Reer LH Door Inner Trim Board       | torn<br>her | 205                       | ✓ |
| Reer LH Door Inner Trim Board clips |             | 20(SN)                    | ✓ |
| Emergency Door Sticker.             | Nec         | 30(SN)                    | ✓ |
| Pull to open Sticker.               |             | 20(SN).                   | ✓ |
| Company Name Sticker.               |             | <del>100(SN)</del> 80(SN) |   |
| 60km/h Sticker.                     | Nec         | 15(SN)                    | ✓ |
| Reer LH Door G( ) Moulding          | Nec         | 284                       | ✓ |
| Reer LH Door G( ) Sealant.          |             | 60(SN)                    | ✓ |
| Reer RH Door                        | Distorted   | 1958                      | ✓ |
| Reer RH Door Lock.                  | Immed       | 325                       | ✓ |
| Reer RH Door Hinge x02              | But         | 102x2=204                 | ✓ |
| Reer RH Door Weatherstripe          | Nec         | 198.                      | ✓ |

PC2165P.

Rear RH Door Inner Trim Board Torn 169 ✓  
Rear RH Door Inner Trim Board Clips <sup>new</sup> 20(SN). ✓  
Rear RH Door Glass Moulding } <sup>new</sup> 284 ✓  
Rear RH Door Glass Sealant. } 60(SN) ✓  
Rear RH Door Company Info Stickers <sup>new</sup> 200(SN). ✓  
Tailgate Panel Glass LH. Lt 385 ✓  
Tailgate Panel Glass Moulding <sup>new</sup> LH. 145 ✓  
Tailgate Panel Glass Sealant. <sup>new</sup> 60(SN) ✓  
Rear Camera. Dazed ~~480(SN)~~ 380(SN) ✓  
Reverse Sensor Damaged 200(SN) ✓  
Rear LH Side Panel. Buckle 3672 ✓  
Rear LH Side Panel Reflector <sup>new</sup> 35 ✓  
Rear LH Side Panel Glass Moulding <sup>new</sup> ~~480~~ 200 ✓  
Rear LH Side Panel Glass Sealant <sup>new</sup> ~~300(SN)~~ 100(SN) ✓  
Rear LH Side Panel Inner Trim. <sup>Torn</sup> 295 ✓  
Rear LH Side Panel Inner Frame <sup>Rips</sup> 3492 +



PC 216SP.

Floor Panel ~~Pyris~~

6800. X

Floor Panel Wooden Board

Cracked 1800(SN). 1000(SN)

Floor Panel Mat.

torn

2500(SN) 1000(SN)

Floor Panel Cross Member

~~Pyris~~

1395. X

~~Rees LH Chassis Member.~~

//

Rees Under Rider.

new

1000(SN). +

Rees Chassis Cross member.

~~Pyris~~

1247. X

Rees LH Seat Cushion.

torn

500(SN). 300(SN)

18258

S-N: 3605.

len 25%: 13693.50

PC2165P.

Panel Beating.

~~4000~~ 2000

Spray Painting,

~~2800~~ 1600

Wiring.

~~100~~ 30

To spray tuff coat.

~~300~~ 250.

To remove upholstery and  
rear seats

~~500~~ 380.

To remove reverse sensor

~~100~~ 50

To remove rear camera.

~~100~~ 50

To transfer rear door fittings.

~~300~~ 200

To remove rear door g/ses.

~~300~~ 160

To remove tailgate Panel g/ses

~~150~~ 80.

To remove side panel g/ses.

~~450~~ 200

To repair and straighten chassis members, ~~800~~ 400.  
5400.

Total: 22688.50

H/S: 17K (Nett Value) 18Days.