

FASTTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

HSR Ao Tony

Not Authorised
 24/11/21
 P/P 12342-31
 7 days

VEHICLE No: SNA 7116H

1PC	REAR WINDSCREEN	shattered		\$1,260.80	✓
1PC	REAR WINDSCREEN MOULDING	nee		\$157.30	✓
1PC	TAILGATE	R		\$1,802.00	X
1PC	TAILGATE OUTER CHROME	cut		\$389.83	✓
1PC	TAILGATE INNER LOCK	11		\$470.36	X
1PC	TAILGATE WEATHERSTRIP	11		\$388.10	X
1PC	TAILGATE 'HYBRID' EMBLEM	svc		\$95.00	X
1PC	TAILGATE INNER TRIM BOARD	11		\$688.10	✓
1PC	REAR BUMPER	dis		\$1,121.00	✓
1PC	REAR BUMPER REFLECTOR O/S	bro	1050.10	\$85.00	✓
1PC	REAR BUMPER SIDE RETAINER O/S	one		\$95.00	✓
1PC	REAR BUMPER BRACKET O/S	R		\$85.00	X
1PC	REAR BUMPER SPLASH SHIELD O/S	del/torn		\$182.10	✓
1PC	TAILLAMP O/S	bro	1210.00	\$1,380.00	✓
1PC	TAILLAMP LOWER GARNISH O/S	dis		\$376.80	✓
1PC	TAILLAMP LOWER GARNISH RETAINER TOP O/S	bro		\$75.00	✓
1PC	TAILLAMP LOWER GARNISH RETAINER LOWER O/S	bro		\$72.00	✓
1PC	TAILLAMP OUTER TOP PANEL O/S	DD		\$188.20	✓
1PC	TAILLAMP OUTER LOWER PANEL O/S	DD		\$180.10	✓
1PC	TAILLAMP INNER HOUSING PANEL O/S	R	159.03	\$199.10	X
1PC	REAR END PANEL	R		\$735.10	X
1PC	REAR END PANEL TOP GARNISH	11		\$281.20	X
1PC	REAR FENDER O/S	DD/suc		\$1,340.80	✓
1PC	REAR FENDER OUTER RAILING O/S	R		\$422.70	X
1PC	REAR FENDER OUTER RAILING GARNISH O/S	mis		\$508.20	✓
1PC	REAR FENDER GLASS O/S	cut/nee		\$931.50	✓
1PC	REAR FENDER INNER TRIM BOARD O/S	del/torn		\$839.67	✓
1PC	REAR AIR CON BLOWER ASSY O/S	one	252	\$3,800.10	✓
1PC	REAR FLOOR PANEL TOP BOARD	11	2761.76	\$855.10	X
				\$19,005.16	

S.NETT

1PC	REAR WINDSCREEN SEALANT	nee	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	nee	\$50.00	40
1PC	REAR WINDSCREEN SOLAR FILM	nee	\$180.00	150
1SET	REAR WINDSCREEN REAR VIDEO CAM	mis	\$500.00	380
1PC	REAR FENDER GLASS SEALANT O/S	nee	\$50.00	40
1PC	REAR FENDER GLASS SOLAR FILM O/S	nee	\$220.00	150
1SET	REAR BUMPER CLIPS	nee	\$50.00	✓
1SET	REAR BUMPER REVERSE SENSOR	11	\$280.00	X

1SET	REAR FENDER INNER TRIM BOARD CLIPS O/S	11	\$50.00	X
1SET	REAR FENDER OUTER RAILING GARNISH CLIPS O/S	11	\$30.00	/
	TO CHECK WIRING		\$50.00	20
	TO DISMANTLE & REPLACED REAR WINDSCREEN		\$150.00	120
	TO TRANSFER TAILGATE MECHANISM	11	\$100.00	X
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$150.00	100
	TO DISMANTLE & REPLACED REAR AIR CON BLOWER		\$150.00	100
	TO DISMANTLE & REPLACED REAR FENDER GLASS O/S		\$150.00	120
	TO REFILL AIR CON GAS		\$120.00	100
	TO SPRAY RUST PROOFING		\$180.00	60
	TO RESET & REPROGRAMME SYSTEM		\$180.00	80
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$1,800.00	1000
	TO PUTTY & SPRAY PAINTING		\$1,800.00	1000
	TOTAL		\$25,295.16	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-11683-09
252
P-876231
S.N-880
L-2700
12342-31