

Verve Motorclinic Pte Ltd (Co.Reg.No:201800568H)

No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB

Singapore 417800

Tel: 67022990 Email: jaronranz92@gmail.com

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC21P00110100	Date of Loss:	19/11/2021
Vehicle Reg. No.:	SGH7239H	Driveable?	YES
Driver Age/Info:	51 / FEMALE	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HUNDANI LIE	Contact No:	+6582989017
Driver:	HUNDANI LIE		
Make/Model:	HONDA JAZZ, 1.4 (A)	Vehicle Reg. Date:	02/07/2006
Vehicle Colour:	Blue	Gen Condition:	Good
Engine No:	123	Chassis No:	JHMGD18506S217807
Odometer:	123456 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 5

Description of Accident/Loss WHILST TRAVELLING STRAIGHT, SUDDENLY VEH NO SMS8390S SLOWED DOWN WITH INTENTION TO TURN RIGHT INTO ESSO PETROL KIOSK.I JAMMED MY BRAKES BUT STILL COULD NOT AVOID THE COLLISION.

Present Location: VERVE MOTORCLINIC PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	884.40
Miscellaneous Items	110.00
Labour	1,430.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	2,424.40

This claim is handled by: JARON RANZ

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Nov 2021)
Parts:	144	HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Verve Motorclinic Pte Ltd/SGH7239H/24/11/2021 15:37	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr		Amount
1	1		Bumper air grille center, front	0.00	0.00	?	*180.00 F
2	1		Bumper clip, front	0.00	0.00	nec✓	*24.00 F
3	1		Bumper, front	0.00	0.00	de✓	*200.00 F
4	1		Headlamp RH	0.00	0.00	cra✓	*145.00 F
5	1		*FRT GRILLE EMBLEM	0.00	0.00	?	*25.00 F
6	1		*FRT BUMPER RETAINER RH/LH	0.00	0.00	nec✓	*30.00 F
7	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	?	*80.00 F
8	1		*FRT SUPPORT PANEL ASSY	0.00	0.00	Rx	*120.00 F

F=Franchise part.

Sub Total (\$\$)	804.00
+ Margin on L,N Items 10.00% (\$\$)	80.40
Total Parts (\$\$)	884.40

Verve Motorclinic Pte Ltd/SGH7239H/24/11/2021 15:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRT NO PLATE WITH BRACKET	bt ✓ 45 50.00
2	1	RADIATOR COOLANT	Xnn 60.00
Sub Total (S\$)			110.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK FRONT ELECTRICAL SYSTEM AND REPAIR WIRE HARNESS	New	30 50.00
2	TO REMOVE AND REINSTALL RADIATOR, A/C CONDENSER AND PIPINGS FOR NECESSARY REPAIRS	New	Xnn 180.00
3	TO REPAIR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	400 600.00
4	TO SPRAY PAINT ON AFFECTED AREA	New	500 600.00
Gross Labour Cost (S\$)			1,430.00

Verve Motorclinic Pte Ltd/SGH7239H/24/11/2021 15:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufikh 97495749/62563561
Not Authorise , Revert
Excess: to be advise
Lumpsum, Resurvey after repair
taufikh@lkkauto.com
4 days
29/11/21 @ 215pm