

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Liu Chun Cheong

Date: 30 Nov 2021

Preliminary Advice

Vehicle No	: SGH7239H	Accident Date	: 19/11/2021
Make	: HONDA JAZZ	Policy No.	: MPC21P00110100
Assignment Date	: 24/11/2021	Excess	: S\$0.00
Date of Inspection	: 29/11/21	Est. Duration of Repair	: 4
Inspection At	: VERVE AUTOCLINIC		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,424.40
Revised Amount	:S\$	1,413.90
Check Items (Estimated)	:S\$	313.50
Total	:S\$	1,727.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	20,510.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,490.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .