

Case Details

Case Reference Number : TAX/11/21/2036
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1432A

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-16715-ID
 Assigned By : Tan Lee Ge #

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
 Accident Date and Time : 20/11/2021 03:20 AM
 Vehicle Age(In Months) : 81

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	de ✓
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	ne ✓
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	Xan
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give	Xan
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	Xan
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	coa ✓
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	Xan
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Give	Xan
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Not Give	Xan
One Time Key In	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	Xan

Total Spare Part Cost 9,393.57
 Lump Sum Discount (%) 20.00
 Final Spare Part Cost 7,514.86

Surveyor Total 528.57
 Lump Sum Dis (%) 20
 Final Sur Total 422.86

1) Date/Time, File Return to?

Final Report

Resurvey No. of Trip:

Survey Fee:

SMRT Recommendation											Surveyor Approval			Remarks
Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main		BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	Xan	
One Time Key In	Main		BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check	?	
One Time Key In	Main		WIRE, ENGINE ROOM, NO.3	1	242.00	242.00	10.00	217.80	Replace	0	0	Not Give	Xan	
One Time Key In	Main		SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Not Give	Xan	
One Time Key In	Main		HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0	Check	?	
One Time Key In	Main		FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair	R	
One Time Key In	Main		NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	Me ✓	
One Time Key In	Main		FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check	?	
One Time Key In	Main		FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	Xan	
One Time Key In	Main		PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Not Give	Xan	
One Time Key In	Main		SEAL, FRONT FENDER TO COWL SIDE LH	1	15.20	15.20	25.00	11.40	Replace	0	0	Not Give	Xan	
One Time Key In	Main		TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	Xan	
One Time Key In	Main		WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Not Give	Xan	
One Time Key In	Main		WHEEL HUB FRT	1	549.70	549.70	25.00	412.28	Replace	0	0	Not Give	Xan	
One Time Key In	Main		MOULDING BODY, LH	1	673.60	673.60	25.00	505.20	Replace	0	0	Not Give	Xan	

Total Spare Part Cost 9,393.57

Surveyor Total 528.57

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 7,514.86

Final Sur Total 422.86

SMRT Recommendation										Surveyor Approval			
Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main		DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	0	0	Not Give	X17
One Time Key In	Main		STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	X17
One Time Key In	Main		MIRROR ASSY, LH	1	1,224.90	1,224.90	10.00	1,102.41	Replace	0	0	Not Give	X17
One Time Key In	Main		COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	1	0	Repair	R
One Time Key In	Main		MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	1	58.77	Replace	sd
Total Spare Part Cost								9,393.57	Surveyor Total		528.57		
Lump Sum Discount (%)								20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost								7,514.86	Final Sur Total		422.86		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	1,014.00	400	
Total:			1,014.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	X17
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	X17
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
5	Main	TO RESPRAY RIM	180.00	0	X17
6	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	X17
7	Main	TO RESPRAY FRONT DOOR LH	378.00	0	X17
Total:			2,034.00	460.00	

Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Main	TO RESPRAY VIEW MIRROR	180.00	60	
Total:		2,034.00	460.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0 <i>XAN</i>	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0 <i>XAN</i>	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 <i>XAN</i>	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0 <i>XAN</i>	
5	Main	TO TRANSFER DOOR MECHANISM	120.00	0 <i>XAN</i>	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	445.32	148.44	
7	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	40	
8	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>XAN</i>	
9	Main	TO WASH AND VACUUM	60.00	0 <i>XAN</i>	
Total:		1,281.32	188.44		

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	7,514.86	422.86
Total Labour Cost	1,014.00	400.00
Total Spray Painting	2,034.00	460.00
Other	1,281.32	188.44
Overall Total	11,844.18	1,471.30
Lump Sum Repair Option		<input checked="" type="checkbox"/>
Lump Sum Total	11,850.00	1,450.00
Surveyor Approved Amount		1,450.00
No of Repair Days*	8	4

Estimator Assesment(\$)

Surveyor Assesment(\$)

LUMP SUM REPAIR / RESURVEY AFTER REPAIR PAINT PHOTO .

Rasul

Surveyor Name

Signature

Save Clear

Survey Date

24/11/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/11/2021 13:52 (SGT)
Date of Accident	20/11/2021 11:20 (SGT)
Exact Location of Accident	Tampines Rd, Singapore
Additional Location Information	TAMPINED ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB1432A

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-21097466MFSH
Cover Note Number	-

DRIVER

Name of Driver	YEN SOON WENG
NRIC No	SXXXX482A

Birth	02/09/1961
Location	Outdoor
Of Driving Pass	19/06/1982
ing experience	39 YEARS AND 5 MONTHS
ender	Male
obile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	-
Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address complement	11
Postcode	-
Is the driver the policyholder?	-
If No, Relationship of the Driver with the Insured	No
Does Driver Own Other Vehicles?	Hirer
Vehicle Registration Number of Other Vehicle Owned by Driver	No
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING IN THE EXTREME RIGHT LANE ALONG TAMPINES ROAD TOWARDS KOVAN AVE 7, SUDDENLY A LORRY WHICH WAS TRAVELLING ON MY LEFT CUT TOWARDS MY LANE AND COLLIDED ONTO THE LEFT PORTION OF MY TAXI. THIRD-PARTY CONTINUED TO DRIVE WITHOUT STOPPING. I WENT AFTER THIRD - PARTY AND MANAGED TO STOP HIM A DISTANCE AWAY.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH6767R
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Commercial vehicle SUN DONJIANG

Policy Number
Policy Class
Address complement
Postal code
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

Others

Techn. Invs (\$

Lump Sum / I.B.I. (\$

Handwritten text, possibly a name or title, written vertically on the left side of the page.

Tampines Rd



Handwritten notes or labels below the diagram, including the word "Block" and other illegible characters.

A large rectangular area containing multiple horizontal lines, likely intended for a signature or additional notes.

Declaration

(I/We hereby declare that the information provided is true and correct)



Handwritten signature or initials.

Handwritten signature.

Name, Position, Organization, Date & Time

Name, Position, Organization, Date & Time

Name, Position, Organization, Date & Time

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **promptly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **accurate and complete as possible**. Any willful misrepresentation or a fraudulent claim will be treated as **fraud** and may result in the **claimant's insurance coverage being terminated**.
4. The **cause and responsibility** of the fault by the driver(s) involved is not an admission of liability on the part of the insurer or company.
5. **Any false representation is to be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the CAA Road Risk Management Centre established by the General Insurance Association of Singapore (GIA) for all policyholders and that subject of the report will be made available upon application by a member of the public.
7. By the submission of this report to the insurer, you hereby consent to the withdrawal of this report if the details of the accident being made available if requested.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workmate and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or transfer my personal data (including photographs and/or film) and any other personal or private information by me or disclosed by my insurer, workmate or the "Personal Information" and to store and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (including those who have insured vehicles involved in this accident and be indirectly related to me (the "Insurers"), the Insurers' law firms, law firms, the Security Authority of Singapore and any relevant government agencies (including, but not limited to, the police), for the purposes of:

(i) investigating, handling and/or dealing with my claims including the settlement of the claims and any non-claim related matters relating to the claims;

(ii) investigating the accident and/or the claims;

(iii) carrying out and/or dealing with my claims (including any handling by other insurers by me);

(iv) administering my claims, including the making of correspondence, statements, notices, receipts or notices to me, or the filing of claims and disclosure of certain personal data about me by being about delivery of the same as well as the on-site review of my claims and packages; and/or

(v) complying with legal obligations in administering, processing, handling and/or dealing with my claims.

(b) I hereby give **permission**:

(i) as insurer(s) to the Insurers/Insured vehicle(s) involved in this accident and the Insurers' law firms, law firms, the Security Authority of Singapore, the Insurers and/or police and my Personal Information for one or more of the above purposes; and

(ii) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party law firms, law firms or agencies (including those law firms, law firms, which may be a third party of Singapore) for one or more of the above purposes.



Policyholder's Signature, Date & Time
Sketch Plan



Driver's Signature (if provided not the Policyholder), Date & Time

Witnessed by: Handling Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHB1432A
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Nov 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1509603
Chassis No.:	JTDKN36U605758448
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	11 Feb 2015
First Registration Date:	11 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Feb 2023
PARF Rebate Amount:	\$5,257.00
COE Expiry Date:	10 Feb 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$52,904.00
COE Rebate Amount:	\$8,018.00
Total Rebate Amount:	\$13,275.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Nov 2021

OK