

Section A - Accident Details

Registration Number	SHB1432A
Case Reference Number	TAX/11/21/2036
Registration Date	11/2/2015
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YEN SOON WENG
Type of Accident	Side Swipe
Accident Date and Time	20/11/2021 11:20 AM
Accident Reported Date and Time	22/11/2021 10:41 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113088
Special Instruction to ARC, if any	TP/ TOWED \$40 / RIGHT FRONT PORTION/CHINA TAIPING - LKK
Prepared Date and Time	22/11/2021 3:48 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$400.00
Total Spray Cost	\$2,034.00	\$460.00
Total Spare Part Cost	\$7,514.86	\$422.86
Total Other Cost	\$1,281.32	\$188.44
TOTAL COST	\$11,844.18	\$1,471.30
Lump Sum Total	\$11,850.00	\$1,450.00 (L/S)
Number of Repair Days	8.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / China Taiping
ARC / Surveyor Sign Off Date	24/11/2021 5:40 PM	24/11/2021 3:12 PM
Signature		
Remarks		LUMP SUM REPAIR / RESURVEY AFTER REPAIR PAINT PHOTO .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2112-0140	Invoice Number	
Quotation Date	08.12.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,014.00	\$400.00 ✓
Total Labour	\$1,014.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO RESPRAY VIEW MIRROR	\$180.00	\$60.00 ✓
Total Spray Painting & Panel Beating	\$2,034.00	\$460.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$445.32	\$148.44 ✓
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$40.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,281.32	\$188.44

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		81740-52040	MIRROR LAMP LH	1.00	\$65.30	10.00	\$58.77	Replace	Replace
		87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	100.00	\$0.00	Replace	Repair
		87940-47310	MIRROR ASSY, LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given
			STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given
		67002-47070	DOOR FRT/LH	0.00	\$894.40	0.00	\$0.00	Replace	Not Given
		75852-47900	MOULDING BODY, LH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given
		43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given

✓ scr
R
X nn
X nn
X nn
X nn
X nn

