

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date: 24 / 11 / 2021

ESTIMATE COSTS OF REPAIR

M/s Car Philosophy Pte Ltd

C/o 160 Sin Ming Drive #05-09

Sin Ming Auto City

Singapore 575722

*Not Authorized
U/Sing @ 7150h
Penny After Rain
9days*

Dear Sir / Madam,

Vehicle no. : SJS 8768 Y - Hyundai i30
Accident date : 23 / 11 / 2021

Quantity	Descriptions	Amount (S\$)
1	1 pc rear bumper fascia	\$ 460.40 —
2	1 pc rear bumper reinforcement	\$ 270.00 —
3	1 pc rear bumper lower lip	\$ 185.00 X
4	2 pcs rear bumper side rainer 1 @ 17.10	\$ 34.20 CT
5	2 pcs rear bumper bracket 1 @ 79.20	\$ 158.40 CT
6	1 pc rear bumper sponge	\$ 129.30 —
7	2 pcs rear bumper no. plate lamp 1 @ 62.10	\$ 124.20 X
8	1 pc rear bumper centre lower cover	\$ 78.00 X
9	2 pcs rear bumper side lower cover 1 @ 14.10	\$ 28.20 CT
10	1 pc o/s tail lamp 447.50	\$ 533.60 —
11	1 pc o/s tail lamp lower clip	\$ 4.00 —
12	1 pc tail gate 1501.00	\$ 2,045.70 —
13	1 pc tail gate inner lock	\$ 166.80 X
14	1 pc tail gate 'Hyundai' emblem	\$ 26.10 —
15	1 pc tail gate 'Hyundai' logo	\$ 31.20 —
16	1 pc tail gate 'i 30 CW' emblem	\$ 42.00 —
17	1 pc tail gate inner trim board	\$ 232.30 X
18	1 pc tail gate lower holder	\$ 236.30 X
19	2 pcs tail gate damper 1 @ 62.40	\$ 124.80 X
20	1 pc o/s rear fender 1248.00	\$ 1,842.00 —
21	1 pc o/s rear fender outer garnish	\$ 128.00 X
22	1 pc o/s rear fender air duct	\$ 32.80 —
23	1 pc o/s rear fender outer shield	\$ 35.00 —
Balance C/FD		\$ 6,948.30

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SJS 8768 Y)

24	1 pc	o/s rear fender inner garnish
25	1 pc	o/s rear wheel house
26	1 pc	o/s rear lower arm
27	1 pc	o/s rear trailing arm
28	1 pc	o/s rear wheel bearing with hub
29	1 pc	o/s rear shock absorber
30	1 pc	rear end panel 489
31	1 pc	rear end panel inner garnish
32	1 pc	o/s rear door
33	1 pc	o/s rear door inner lock
34	1 pc	o/s rear door rubber
35	1 pc	rear spare tyre board
36	1 pc	rear exhaust box
37	1 pc	rear exhaust box garnish
38	1 pc	rear weather-strip
39	1 pc	rear windscreen glass molding

Less 20%

\$	6,948.30
\$ CM	163.00
\$ R	1,095.50
\$ DM	239.60
\$ B	225.80
\$ B	394.50
\$ B	223.00
\$ M	499.30
\$ CM	59.00
\$ R	1,837.70
\$ R	246.50
\$ S	124.80
\$ S	316.70
\$ B	711.20
\$ S	113.30
\$ S	84.40
\$ M	109.00
\$	13,391.60
\$	2,678.32
\$	10,713.28

40	1 set	rear bumper reverse sensor
41	1 pc	rear bumper no. plate
42	1 pc	rear end panel seal
43	1 pc	rear windscreen glass inner seal
44	1 pc	rear windscreen glass inner gum

Balance C/FD

\$ S/R	350.00	sn 2005m
\$ M	100.00	sn X
\$ M	250.00	sn 305m
\$ M	60.00	sn 305m
\$ M	60.00	sn 405m
\$	11,533.28	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SJS 8768 Y)

\$ 820.00

Labour charges

\$ 2,200.00 1200

To putty and spray painting

\$ 1,800.00 1200

Re-seal anti rust

\$ 200.00 90

To check, replace, repair wiring

\$ 120.00 20

Remove and refix rear windscreen glass

\$ 160.00 120

Remove and refix cushion seat, garnish, carpet, etc

\$ 180.00 120

Remove and refix exhaust box

\$ 120.00 60

Remove and refix rear undercarriage

\$ 380.00 140

To check wheel alignment

\$ 120.00 60

Remove and refix rear reverse sensor

\$ 100.00 50

Total

\$ 6,200.00

* Tandy charges (Kig Lohy) \$ 180 ? (Bill)