



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /ANG PAU YONG Reg No/Reg Date SLJ1837B / 30/11/201 Date In/Mileage / 0 Chassis No KNAFX411MH5668425 Engine No G4FGGH658434 Make/Model KIA/FORTE K3 1.6 A EX BRQ Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/11/2021/ 09:40	BLK	282 / Kevin Leong	42969			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1200.00
REPLACE FRT BUMPER, SUPPORT & AFFECTED AREA								350.00
E PNT98000								120.00
PAINT WORK ON FRT BUMPER PANEL								80.00
E PNT88000								40.00
REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR								30.00
M SUNDRY								120.00
TO TOP UP AIRCON GAS								50.00
M SUNDRY								30.00
PERFORM RUST PREVENTION								120.00
A 54900099								50.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901								30.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								1365.60
M SUNDRY								540.00
TO SUPPLY FRT NUMBER PLATE WITH FRAME								506.40
M SUNDRY								14.40
SUNDRIES					1.00	1707.00	20.00	44.00
M LAMP ASSY-HEAD,LH	BR				1.00	675.00	20.00	4.80
M CARRIER ASSY-FRONT END MODULE	BR				1.00	633.00	20.00	26.40
M COVER-FR BUMPER	BR				1.00	18.00	20.00	67.20
M MOULDING-FRT BPR LICENSE PLATE	BR				1.00	55.00	20.00	91.20
M LIP ASSY-FRONT BUMPER	BR				1.00	6.00	20.00	396.80
M DUCT ASSY-AIR CURTAIN,LH	BR				1.00	33.00	20.00	10.40
M AIR DUCT-FR BUMPER,LH	BR				1.00	84.00	20.00	262.40
M ABSORBER-FRONT BUMPER ENERGY	BR				1.00	114.00	20.00	25.60
M STIFFNER-FR BPR LWR	BR				1.00	496.00	20.00	
M RAIL ASSY-FR BUMPER	BR				1.00	13.00	20.00	
M BRACKET-FR BUMPER SIDE MTG,LH	BR				1.00	328.00	20.00	
M GRILLE ASSY-RADIATOR	BR				1.00	32.00	20.00	
M ORNAMENT-KIA NO.115	BR				1.00			

Estimate

Steve (LKK)

26/11/21, 9:30am

OD- M PL

Exec - ?

Confirm & accepted by

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is a "third party" task

Authorized signatory and company stamp

P/P, M PL sy
48 days
7% GST on
5375.20

Nett

5375.20

Total Payable

5,375.20

376.26

5,751.46

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.