



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 05.11.2021
Emailed : 20.12.2021, 2.15pm
Date survey : 26.11.2021

VEHICLE NO : SLJ 1837 B
MODEL : KIA FORTE K3 1.6 A EX
WIP : 42969

Material	:	\$	3,229.60
Labour	:	\$	1,370.00
Sub-Total	:	\$	4,599.60
	:		-
Less Excess	:	\$	300.00
Total	:	\$	4,299.60
GST 7%	:	\$	300.97
Grand Total	:	\$	4,600.57
Finalise By/Date	:	LOI / 20/12/2021	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 26/11/2021	Cust No/Name	LCV15282/ANG PAU YONG
	Reg No/Reg Date	SLJ1837B*KC17/ 30/11/2016
	Date In/Mileage	26/11/2021/ 81998
	Chassis/Package	KNAFX411MH5668425 /@
	Engine No	G4FGGH658434
	Make/Model	KIA/FORTE K3 1.6 A EX BRQ
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	17/12/2021/ 09:44	BLK	260 / AiTing	42969

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				400.00
E PNT98000 RESpray ON FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME				350.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				120.00
M SUNDRY SUNDRIES				20.00
S SPECIALISTJOB SUPPLY & REPLACE FRONT NUMBER PLATE WITH FRAME				50.00
E PNT88000 REPLACE FRONT SUPPORT PANEL → Supp.				400.00
X EXC INSURANCE EXCESS				-300.00
X LAMP ASSY-HEAD,LH	1.00	✓ 1707.00	20.00	1365.60
X CARRIER ASSY-FRONT END MODULE	1.00	? 675.00	20.00	540.00
X COVER-FR BUMPER	1.00	✓ 633.00	20.00	506.40
X MOULDING-FRT BPR LICENSE PLATE	1.00	✓ 18.00	20.00	14.40
X ABSORBER-FRONT BUMPER ENERGY	1.00	? 84.00	20.00	67.20
X RAIL ASSY-FR BUMPER	1.00	? 496.00	20.00	396.80
X GRILLE ASSY-RADIATOR	1.00	✓ 328.00	20.00	262.40
X ORNAMENT-KIA NO.115	1.00	✓ 32.00	20.00	25.60
X GARNISH-RADIATOR GRILLE,UPR	1.00	✓ 54.00	20.00	43.20
X CLIP → Supp.	10.00	1.00	20.00	8.00
Z TEXT AIG OD CLAIM DOA : 05.11.21 SURVEYOR STEVE-LKK 26.11.21 POLICY NO : 2100492176-04 REPAIR 3D+1D=4D				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,229.60	Nett	4,299.60
Labour	1,300.00	7% GST on	300.97
Standard Menu	0.00		
Specialist Job	50.00	Total Payable	4,600.57
Diagnostics Job	0.00		
Sundry/Others	-280.00		
Total(w/o GST)	4,299.60		

This is not an official tax invoice.
This is a computer generated document, no signature is required.




Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SLJ 1837 B

<u>Materials</u>		<u>Cost (\$)</u>
1	Garnish-Radiator Grille, Upr	54.00 <i>BR</i>
2	Clips (X10)	10.00 <i>nec</i>
Total Materials		64.00
Less 20% discount		12.80
Total after discount		51.20
<u>Labour</u>		<u>Cost (\$)</u>
1	Replace front support panel	400.00 <i>✓</i>
Total labour		400.00
Total amount		451.20
7% GST		31.58
Grand total		<u>\$ 482.78</u>

Thank You.
Yours faithfully


LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SLJ 1837BWIP: 42969 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Carrier Assy - Front End Module	? / SUPP			64101 A7600
2	Absorber Ficht Bumper Energy	? / SUPP			86520 A7800
3	Grainish Radiator Grille UPR	? / SUPP			86358 A7800
4	Clip Front Bumper	? / SUPP			86595 27500
5	Rail Assy Front Bumper	? / SUPP			86530 A7600
6	Renew Front Support Pune A400	? / SUPP			
7	repair working Day XI	? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	1/12	
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Forte K3 1.6SURVEYOR: Steve - LKL



CERATO/FORTE../2017/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Engine / DTC

ABS / DTC

Save



8/8

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
SJB	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No Current DTC

S/W Ver. M-E-K-01-00-0259

VCI Ver. 02.63

ECU Ver. M-E-K-01-00-0199

OS Ver. Android 10