

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
 GST:M9-0009639-E RCB NO:06470300B

## SURVEYOR COPY

M/S : HISAKA (SINGAPORE)PTE LTD  
 63 SUNGEI KADUT LOOP  
 HISAKA INDUSTRIAL BUILDING  
 SINGAPORE 729484

Estimate No: MC1902296  
 Date: 22 Nov 2021  
 Policy No: GA575507/1  
 Veh Reg No: SKU2082J  
 Make/Model: TOYOTA CAMRY  
 HYBRID 2.5G CVT

ATTN:

Your Ref No: SKU2082J  
 Claim Type: Third Party - india  
 Accident Date: 17/11/2021  
 TP Veh Reg No: SLL9594M

LIC 1030

*Not Authorized  
 Return by 3 days*

### Estimate Repair Cost to Vehicle No :SKU2082J

Description	Quantity	List Price	Amount
		SS	SS
<b>SPARE PARTS</b>			
1 REAR BOOT	1 PC	1,143.70	
2 REAR BOOT EMBLEM	1 PC	47.90	
3 REAR BOOT CAMRY LOGO	1 PC	70.20	X
4 REAR BOOT HYBRID SYNERGY DRIVE LOGO	1 PC	65.80	
5 REAR BOOT LAMP LH & RH	2 PC	1,201.90	X
6 REAR BOOT NO PLATE LAMP LH & RH	2 PC	323.40	X
7 REAR BOOT NO PLATE GARNISH	1 PC	211.67	X
8 REAR BOOT LOCK	1 PC	498.10	X
9 REAR BOOT LOCK CATCH	1 PC	28.90	X
10 REAR BOOT RUBBER	1 PC	227.80	X
11 TAILAMP LH & RH	2 PC	1,561.90	X
12 TAILAMP LOWER BEAM LH & RH	2 PC	245.20	X
13 TAILAMP COVER LH & RH	2 PC	135.60	X
14 REAR BUMPER	1 PC	721.90	
15 REAR BUMPER LOWER GARNISH	1 PC	433.70	
16 REAR BUMPER LOWER GARNISH REFLECTOR LH & RH	2 PC	163.80	X
17 REAR BUMPER SIDE RETAINER LH & RH	2 PC	262.14	X
18 REAR BUMPER CLIPS	12 PC	54.00	
19 REAR BUMPER REINFORCEMENT	1 PC	399.84	?
20 REAR END PANEL GARNISH	1 PC	399.84	X
21 EXHAUST PIPE TAIL	1 PC	175.70	X
		8,372.99	
	Less 25%	2,093.25	6,279.74
<b>Special Nett</b>			
22 REAR CAMERA - CHECK PRICE	1 PC	0.0000	X
23 NUMBER PLATE	1 PC	35.00	X
24 REVERSE SENSOR	1 SET	200.00	X
		235.00	235.00
<b>LABOUR</b>			
25 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	156
26 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	506
27 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	306

*Zila  
 Ah Lim Motor Company*

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg  
GST:M9-0009639-E RCB NO:064703008

**SURVEYOR COPY**

M/S : HISAKA (SINGAPORE)PTE LTD  
63 SUNGEI KADUT LOOP  
HISAKA INDUSTRIAL BUILDING  
SINGAPORE 729484

Estimate No: MC1902296  
Date: 22 Nov 2021  
Policy No: GA575507/1  
Veh Reg No: SKU2082J  
Make/Model: TOYOTA CAMRY  
HYBRID 2.5G CVT

ATTN:

Your Ref No: SKU2082J  
Claim Type: Third Party  
Accident Date: 17/11/2021  
TP Veh Reg No: SLL9594M

## Estimate Repair Cost to Vehicle No :SKU2082J

Description	Quantity	List Price	Amount
		S\$	S\$
28 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIRREAR END PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	400
29 TO SPRAY REAR BOOT,REAR BUMPER,REAR END PANEL.	1 PC	700.00	400
		1,460.00	1,460.00
		Total	S\$ 7,974.74
		Add GST @ 7%	558.23
		Total Amount Payable	S\$ 8,532.97

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FIVE HUNDRED THIRTY TWO AND CENTS NINETY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

For AH LIM MOTOR COMPANY

  
Ah Lim Motor Company

AUTHORISED SIGNATURE

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: