

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : HISAKA (SINGAPORE)PTE LTD  
63 SUNGEI KADUT LOOP  
HISAKA INDUSTRIAL BUILDING  
SINGAPORE 729484

ATTN:

Your Ref No: CC4/GRB21011976  
Claim Type: Third Party  
Accident Date: 17/11/2021  
TP Veh Reg No: SLL9594M

**Claim No:** ~~MC1902296~~  
**No:** MF1902150  
**Date:** 19 Mar 2022  
**Policy No:** GA575507/1  
**Veh Reg No:** SKU2082J  
**Make/Model:** TOYOTA CAMRY  
HYBRID 2.5G CVT  
**Chassis No:** AXVH701031457  
**TP Ins Co:** INDIA

**DRAFT FINALISATION**

**DRAFT FINALISATION**

## Repair Cost to Vehicle No (For Finalization):SKU2082J

Description	Quantity	List Price	Amount
		S\$	S\$
<b>SPARE PARTS</b>			
1 REAR BOOT	1 PC	1,143.70	
2 REAR BOOT EMBLEM	1 PC	47.90	
3 REAR BOOT HYBRID SYNERGY DRIVE LOGO	1 PC	65.80	
4 REAR BUMPER	1 PC	721.90	
5 REAR BUMPER LOWER GARNISH	1 PC	433.70	
6 REAR BUMPER CLIPS	12 PC	54.00	
7 REAR BUMPER REINFORCEMENT	1 PC	399.84	
		2,866.84	
	Less 25%	716.71	2,150.13
<b>LABOUR</b>			
8 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	15.00	
9 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
10 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	
11 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIRREAR END PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	
12 TO SPRAY REAR BOOT,REAR BUMPER,REAR END PANEL.	1 PC	400.00	
		895.00	895.00
		Total	S\$ 3,045.13
		Add GST @ 7%	213.16
		Total Amount Payable	S\$ 3,258.29

TOTAL: SINGAPORE DOLLAR THREE THOUSAND TWO HUNDRED FIFTY EIGHT AND CENTS TWENTY NINE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 26/11/2021

For AH LIM MOTOR COMPANY  
**AH LIM MOTOR COMPANY**  
No. 10 Ang Mo Kio Industrial Park 2A  
#01-09 AMK Autopoint, Singapore 568047  
Tel: 6483 1244 FAX: 6483 6170

AUTHORISED SIGNATURE

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg  
 GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : HISAKA (SINGAPORE)PTE LTD  
 63 SUNGEI KADUT LOOP  
 HISAKA INDUSTRIAL BUILDING  
 SINGAPORE 729484

Estimate No: MC1902296  
 Date: 22 Nov 2021  
 Policy No: GA575507/1  
 Veh Reg No: SKU2082J  
 Make/Model: TOYOTA CAMRY  
 HYBRID 2.5G CVT

ATTN:

Your Ref No: SKU2082J  
 Claim Type: Third Party - media  
 Accident Date: 17/11/2021  
 TP Veh Reg No: SLL9594M

*LIC 1.030*  
*Not Authorized*  
*Resurvey B4paim*  
*3 days*

**Estimate Repair Cost to Vehicle No :SKU2082J**

Description	Quantity	List Price	Amount
		SS	SS

**SPARE PARTS**

1 REAR BOOT	1 PC	<i>Bu</i> 1,143.70	<input checked="" type="checkbox"/>
2 REAR BOOT EMBLEM	1 PC	<i>bu</i> 47.90	<input checked="" type="checkbox"/>
<del>3 REAR BOOT CAMRY LOGO</del>	<del>1 PC</del>	<del><i>bu</i> 70.20</del>	<del><input checked="" type="checkbox"/></del>
4 REAR BOOT HYBRID SYNERGY DRIVE LOGO	1 PC	<i>bu</i> 65.80	<input checked="" type="checkbox"/>
<del>5 REAR BOOT LAMP LH &amp; RH</del>	<del>2 PC</del>	<del><i>bu</i> 1,201.90</del>	<del><input checked="" type="checkbox"/></del>
<del>6 REAR BOOT NO PLATE LAMP LH &amp; RH</del>	<del>2 PC</del>	<del><i>bu</i> 323.40</del>	<del><input checked="" type="checkbox"/></del>
<del>7 REAR BOOT NO PLATE GARNISH</del>	<del>1 PC</del>	<del><i>bu</i> 211.67</del>	<del><input checked="" type="checkbox"/></del>
<del>8 REAR BOOT LOCK</del>	<del>1 PC</del>	<del><i>bu</i> 498.10</del>	<del><input checked="" type="checkbox"/></del>
<del>9 REAR BOOT LOCK CATCH</del>	<del>1 PC</del>	<del><i>bu</i> 28.90</del>	<del><input checked="" type="checkbox"/></del>
<del>10 REAR BOOT RUBBER</del>	<del>1 PC</del>	<del><i>bu</i> 227.80</del>	<del><input checked="" type="checkbox"/></del>
<del>11 TAILAMP LH &amp; RH</del>	<del>2 PC</del>	<del><i>bu</i> 1,561.90</del>	<del><input checked="" type="checkbox"/></del>
<del>12 TAILAMP LOWER BEAM LH &amp; RH</del>	<del>2 PC</del>	<del><i>bu</i> 245.20</del>	<del><input checked="" type="checkbox"/></del>
<del>13 TAILAMP COVER LH &amp; RH</del>	<del>2 PC</del>	<del><i>bu</i> 135.60</del>	<del><input checked="" type="checkbox"/></del>
14 REAR BUMPER	1 PC	<i>Bu</i> 721.90	<input checked="" type="checkbox"/>
15 REAR BUMPER LOWER GARNISH	1 PC	<i>bu</i> 433.70	<input checked="" type="checkbox"/>
<del>16 REAR BUMPER LOWER GARNISH REFLECTOR LH &amp; RH</del>	<del>2 PC</del>	<del><i>bu</i> 163.80</del>	<del><input checked="" type="checkbox"/></del>
<del>17 REAR BUMPER SIDE RETAINER LH &amp; RH</del>	<del>2 PC</del>	<del><i>bu</i> 262.14</del>	<del><input checked="" type="checkbox"/></del>
18 REAR BUMPER CLIPS	12 PC	<i>bu</i> 54.00	<input checked="" type="checkbox"/>
19 REAR BUMPER REINFORCEMENT	1 PC	<b>DAM</b> 399.84	<input checked="" type="checkbox"/> <i>photo</i>
<del>20 REAR END PANEL GARNISH</del>	<del>1 PC</del>	<del><i>bu</i> 399.84</del>	<del><input checked="" type="checkbox"/></del>
21 EXHAUST PIPE TAIL	1 PC	<i>bu</i> 175.70	<input checked="" type="checkbox"/>
		8,372.99	
	Less 25%	2,093.25	6,279.74

**Special Nett**

<del>22 REAR CAMERA - CHECK PRICE</del>	<del>1 PC</del>	<del><i>bu</i> 0.0000</del>	<del><input checked="" type="checkbox"/></del>
<del>23 NUMBER PLATE</del>	<del>1 PC</del>	<del><i>bu</i> 35.00</del>	<del><input checked="" type="checkbox"/></del>
<del>24 REVERSE SENSOR</del>	<del>1 SET</del>	<del><i>bu</i> 200.00</del>	<del><input checked="" type="checkbox"/></del>
		235.00	235.00

**LABOUR**

25 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>15/</i>
26 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<i>50/</i>
27 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	<i>30/</i>

*Ah Lim Motor Company*

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300E

**SURVEYOR COPY**

M/S : HISAKA (SINGAPORE)PTE LTD  
63 SUNGEI KADUT LOOP  
HISAKA INDUSTRIAL BUILDING  
SINGAPORE 729484

Estimate No: MC1902296  
Date: 22 Nov 2021  
Policy No: GA575507/1  
Veh Reg No: SKU2082J  
Make/Model: TOYOTA CAMRY  
HYBRID 2.5G CVT

ATTN:

Your Ref No: SKU2082J  
Claim Type: Third Party  
Accident Date: 17/11/2021  
TP Veh Reg No: SLL9594M

## Estimate Repair Cost to Vehicle No :SKU2082J

Description	Quantity	List Price	Amount
28 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR END PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	S\$ 600.00	400
29 TO SPRAY REAR BOOT,REAR BUMPER,REAR END PANEL.	1 PC	700.00	400
		1,460.00	1,460.00
		Total	S\$ 7,974.74
		Add GST @ 7%	558.23
		Total Amount Payable	S\$ 8,532.97

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FIVE HUNDRED THIRTY TWO AND CENTS NINETY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

For AH LIM MOTOR COMPANY

*Zha*  
Ah Lim Motor Company

AUTHORISED SIGNATURE

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: