|--|--|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	tionale Des Experts En A	utomob	pile			
	LONPAC INSURAI	NCE BHD	F	Ref:	CS3/LPC21011982/Bqf3			
	300 BEACH ROAD #17-04/07 THE CO) DNCOURSESINGAPORE 19955		Date:	25/11/2021			
			C	Code:	LPC2			
	Policy Particulars :- (THIRD PARTY CLAIM)							
	Insured Veh.	GBG 9884X	Veh. Inspected		GBA 1411L			
	Policy No.		Coverage (\$)		0.00			
	Claim No.	20/21/21/VC05/025181	Excess (\$)		0.00			
	Assign From	GERALD POH	Assign Date		25/11/2021			
	Vehicle Particulars & Condition							
	Make & Model		c.c		0			
	Engine No.	HIDDEN	Year of Reg.					
	Chassis No.		Colour					
	Odometer	-	Steering					
	Brakes	Modification						
	General							
		Cond	litions of Tyres					
		Size	Make		Balance			
	R/H Front Tyre				mm			
	L/H Front Tyre				mm			
	R/H Rear Tyre				mm			
	L/H Rear Tyre				mm			
	Description of Damages							
		Gene	ral Information					
	Accident Date	23/11/2021	Inspection Date		25/11/2021			
	Survey held at	GUAN AUTO SERVICE						
	BLK12 #01-59 SIN MING INDUSTRIAL ESTATE SECTOR B SINGAPORE 575656							
a.		Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.							