

ASS. REC. BY:

TGUW

REF:

CS3/LPC 2011982/Bgf3

Jian Chen

ASSIGNMENT

From:

Date: 25/11/2021

Veh No:

GBA 1411L

Yr Regn:

15/3/2007

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

GBA 1411L

Make:

Toyota Hiace MT

C.C. 2982

at Workshop m/s

Guan Auto Service

Colour:

Silver

A/C: Insured / Std / NI / NA

of BKR #01-59 In Ming Est Sect B

Sp. Reading

376412

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

1KD1599192

Policy No.

C/No:

JTEHT02P30-0002823

Claims No.

20/21/21/VC05/025181

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Knotted / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Knotted / Jammed / Leaked / Burnt or

Make of Veh:

Modi: NI / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

4,000/-

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

Tyre Size:

F: 195/15 Yokohama

R: 195/15 CST

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

23/11/2021

D.O.I.

25/11/2021

Survey held at

Guan Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: 2,000/- - 10,000/-

Survey photos taken on Thu 25/11/2021 @ 2:44:48 PM

Resurvey photos taken on Fri 26/11/2021 @ 11:46:18 AM

Recommended car: LS \$9300.00 (Red \$4900, 35%)

MV 4,000/-

PV 12,953/-

NV 2,047/-

TGUW

3/2/2022

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

14

1) 03/02 Typist

☐

Final Report

Resurvey No. of Trip:

1

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

1

S + RS, SI

☐

Interview (\$

Photos

☐

Tech. Invs (\$

Chassis

☐

Weekend (\$

TOTAL

Report Formist:

TP

Lump Sum

9300

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS					2007	
A) SPARE PARTS	QTY	ASSESSED	ORIGINAL	REVISED		
	PC/SET	CONDITION	QUOTATION	QUOTATION		
1 Rear tail gate	1	Dented	\$ 2,098.00	\$ 1755.00 2,098.00	DD	✓
2 Rear tail gate lift absorber L/R	1 set	Bent	\$ 180.00	\$ 180.00	NDX	
3 Rear tail gate lock	1	Jammed	\$ 270.10	\$ 270.10	JMV	✓
4 Rear tail gate lock remote mechanism	1	Bent	\$ 295.40	\$ 295.40	BTJ	✓
5 Rear tail gate lock catch	1	Bent	\$ 28.10	\$ 28.10	BTJ	✓
6 Rear tail gate license lamp moulding	1	Sheared off	\$ 257.90	\$ 257.90	MTJ	✓
7 Rear end panel top metal plate	1	Bent	\$ 117.00	\$ 117.00	DD	✓
8 Rear end panel (inner)	1	Dented	\$ 675.00	\$ 566.10 675.00	DD	✓
9 Rear end panel (outer)	1	Dented	\$ 456.00	\$ 336.70 456.00	DD	✓
10 Rear tail gate weather-strip	1	Cut	\$ 119.50	\$ 119.50	TN	✓
11 Rear tail lamp L/R @ \$365.10	2	Broken/Cracked	\$ 730.20	\$ 519.80 730.20	BR	✓
12 Rear tail lamp corner panel L/R @ \$127.00	2	Cracked	\$ 254.00	\$ 75.20 254.00	DD	✓
13 Rear tail gate windscreen glass	1	Shattered	\$ 957.40	\$ 957.40	BR	✓
14 Rear tail gate wiper motor assy	1	Jammed	\$ 368.60	\$ 368.60	BTJ	✓
15 Rear tail gate top trim garnish	1	Deformed	\$ 247.00	\$ 247.00	BR	✓
16 Rear tail gate inner board	1	Torn	\$ 219.40	\$ 186.70 219.40	BR	✓
17 Rear tail gate third brake light	1	Cracked	\$ 194.00	\$ 194.00	BR	✓
18 Rear body side panel RH	1	Mangled/Dented	\$ 3,512.80	\$ 1795.50 3,512.80	DD	✓
19 Sliding door rail moulding RH	1	Serviceable	\$ 182.00			
20 Rear bumper	1	Dislodged	\$ 597.50	\$ 517.20 597.50	BTJ	✓
21 Rear bumper side retainer L/R @ \$38.40	2	Cracked	\$ 76.80	\$ 76.80	NECV	✓
22 Rear bumper bracket L/R @ \$37.10	2	Bent	\$ 74.20	\$ 74.20	BTJ	✓
23 Rear air duct L/R @ \$47.00	2	Torn	\$ 94.00	\$ 47.00 94.00	BR	✓
24 Rear exhaust pipe	1	Bent	\$ 1,482.90	\$ 931.60 1,482.90	BTJ	✓
25 Rear exhaust pipe mounting hook	3	Torn	\$ 68.00	\$ 68.00	NECV	✓
26 Rear spare tyre bracket	1	Bent	\$ 384.60	\$ 172.10 384.60	BTJ	✓
		Less 25%	\$ 9976.90	\$ 2494.23		
			\$ 7482.68	\$ 10,455.30		
B) S/NETT ITEM						
27 Rear bumper clips	1 set	Necessary	\$ 34.00	\$ 30.00 34.00	NECV	✓
28 Rear tail gate windscreen glass moulding	1	Necessary	\$ 219.00	\$ 60.00 219.00	NECV	✓
29 Rear tail gate wiper arm	1	Bent	\$ 140.00	\$ 57.60 140.00	BTJ	✓
30 Rear tail gate back view mirror	1	Bent	\$ 174.00	\$ 89.00 174.00	BR	✓
31 Rear tail gate license lamp @ \$34.00	2	Cracked	\$ 64.00	\$ 64.00	CRV	✓
32 Rear tail gate emblem	1	Necessary	\$ 71.60	\$ 39.00 71.60	NECV	✓
33 Rear tail gate '70 km/h' sticker	1	Necessary	\$ 18.00	\$ 10.00 18.00	NECV	✓
34 Rear tail gate '8 pax' sticker	1	Necessary	\$ 18.00	\$ 10.00 18.00	NECV	✓
35 Rear bumper reverser sensor L/R	1 set	Malfunction	\$ 250.00	\$ 200.00 250.00	SC	✓
36 Rear recorder camera	1 set	Malfunction	\$ 280.00	\$ 150.00 280.00	SC	✓
37 Rear number plate	1	Cracked	\$ 50.00	\$ 30.00 50.00	BR	✓
Parts Total :			\$ 11,773.90	\$ 11,637.40		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is done without prejudice basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Insurance Loss Assessors/Adjusters, Inspection and Evaluation

739.60

C) LABOUR CHARGES & MISC

38	Putty & spray painting affected portions including supply of paint materials.	\$ 1,800.00	\$ 1,500.00 12.00.00 ✓
39	Remove damaged parts, knock out dents, straighten, jack out damaged panel, cutting, welding, remove & reinstall necessary fittings to facilitate, repairs, reshape, refit, adjust, replace and realign all relevant parts.	\$ 2,800.00	\$ 2,000.00 16.00 ✓
40	To mount vehicle onto chassis alignment bench, straighten floor panel & rear chassis frame, repair and conduct alignment.	\$ 600.00	\$ 450.00 200.00 ✓
41	To supply & installation rear whole back panel sticker include artwork. (Attached invoice)	\$ 1,200.00	\$ * 1,200.00 * invoice NEC NNX
42	To check, refix instrument panel & glove compartment	\$ 250.00	\$ 100.00 NNX
43	Check wiring, lighting system & centre locking system for proper function.	\$ 80.00	\$ 50.00 ✓
44	To cavity preservation on all affected portions & re-seal body panel joint.	\$ 250.00	\$ 100.00 90.00 ✓
45	To transfer tail gate mechanism.	\$ 80.00	\$ 40.00 ✓
46	To replace rear windscreen glass.	\$ 180.00	\$ 120.00 ✓
47	To drill holes & reinstall rear bumper reverse sensor.	\$ 160.00	\$ 120.00 60.00 ✓
48	To supply rear windscreen glass sealant	\$ 50.00	\$ 40.00 NNX
49	To straighten, remove & reinstall rear exhaust pipe system.	\$ 180.00	\$ 150.00 80.00 ✓
50	To provide towing services.	\$ 120.00	\$ 100.00 NNX
Labour Total :		\$ 7,750.00	\$ 6,130.00 3440.00
Total Parts and Labour		\$ 19,523.90	\$ 17,767.40

FINAL LUMP SUM ADJUSTMENT

\$ 14,200.00

POINT OF IMPACT

The impact was confined to the rear portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

* To provide invoice to amend car

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$14,200.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
KTO Automobile Assessors



Ong Ah Keng (CAE, AMIMI, MSAAA)
Automotive Appraiser

Parts	7482.68
SN	739.60
Labour	3440.00
	<hr/> 11662.28
@20%	2332.46
	<hr/> 9329.82

LS 9300/2

Repair days 14

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	782N
Vehicle Details	
Vehicle No.:	GBA1411L
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Feb 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1KD1599192
Chassis No.:	JTFHT02P300002823
Maximum Power Output:	-
Open Market Value:	\$24,590.00
Original Registration Date:	15 Mar 2007
First Registration Date:	15 Mar 2007
Transfer Count:	3
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$20,325.00
COE Rebate Amount:	\$19,953.00
Total Rebate Amount:	\$19,953.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 03 Feb 2022

OK

MV 41,000/2
PV 19,953/2
NV 21,047/2

TGum Mui
3/2/2022

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/11/2021 12:31 (SGT)
Date of Accident	23/11/2021 17:26 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	THOMSON RD BESIDE THOMSON 800
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBA1411L

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	YU SHUEN TRADING PTE LTD
Company Reg No	1XXXXX782N
Email Address	YUSHUENTRADING@GMAIL.COM
Mobile Phone No	(Phone) +65-90699919
Alternative Phone No	+65-90699919

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Hiace
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2988

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	50856332270-04
Cover Note Number	-

DRIVER

Name of Driver	GUNASEKARAN RAGAVAN
NRIC No	GXXXX837T

Date Of Birth	14/03/1991
Occupation	Outdoor
Date Of Driving Pass	17/07/2018
Driving experience	3 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90699919
Alt. Phone Number	-
Email Address	YUSHUENTRADING@GMAIL.COM
Address	146, POTONG PASIR AVE 1, #02-125
Address complement	-
Postcode	350146
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	PASSENGER
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG9884X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



[Handwritten signature]

CITY AUTO PTE LTD
Blk 3 Sin Ming Road
#01-534/535 Sin Ming Ind Est
Singapore 575613
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)

Policyholder's Signature / Date & Time
24/11/21

Driver's Signature (if driver is not the policyholder) / Date & Time
24/11/21

Witnessed by Reporting Centre Personnel

Sketch Plan

