

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2111-282-TG
DATE : 25-Nov-2021
POLICY NO. : P10508679R00
VEHICLE REG. NO. : **SKU2627M**
VEHICLE MAKE : MAZDA 3-1.5 L 4-DOOR SEDAN**TO** Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street, #04-#05 IOB Building
Singapore 049711
Tel: 6347 6100 Fax: 6224 4174 / 6225 7743**FOR SURVEYOR**

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>				
1	Rear Bumper	1	\$ 1,080.00	\$ 1,080.00
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 40.00	\$ 40.00
4	Rear Bumper Bracket RH	1	\$ 50.00	\$ 50.00
5	Rear Bumper Tow Eye Cover	1	\$ 30.00	\$ 30.00
6	End Panel	1	\$ 380.00	\$ 380.00
7	Rear Bumper Reflector RH	1	\$ 50.00	\$ 50.00
Total Spare Parts				\$ 1,630.00
<u>SPECIAL NETT</u>				
7	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 200.00
<u>LABOUR</u>				
8	Spray Painting Whole Rear Bumper	1	\$ 300.00	\$ 300.00
9	Remove, Replace and Refit Rear Affected Area	1	\$ 300.00	\$ 300.00
10	Remove, Replace and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
11	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 710.00
Amount Before Excess				\$ 2,540.00
Add GST @ 7%				177.80
Total Amount Payable				\$ 2,717.80

Estimate prepared by: **RAZALI**

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.