

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2111-282-TG

DATE : 25-Nov-2021

POLICY NO. : P10508679R00

VEHICLE REG. NO. : SKU2627M

VEHICLE MAKE : MAZDA 3-1.5 L 4-DOOR SEDAN

TO Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street, #04-#05 IOB Building
Singapore 049711

Tel: 6347 6100 Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>OK</i>	1	\$ 1,080.00	\$ 1,080.00
2	Rear Bumper Clips <i>nk</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH <i>X nn</i>	1	\$ 40.00	\$ 40.00
4	Rear Bumper Bracket RH <i>X nn</i>	1	\$ 50.00	\$ 50.00
5	Rear Bumper Tow Eye Cover <i>CR4</i>	1	\$ 30.00	\$ 30.00
6	End Panel <i>X nn</i>	1	\$ 380.00	\$ 380.00
7	Rear Bumper Reflector RH <i>X nn</i>	1	\$ 50.00	\$ 50.00
Total Spare Parts				\$ 1,630.00
SPECIAL NETT				
7	Reverse Sensor <i>phd</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 200.00
LABOUR				
8	Spray Painting Whole Rear Bumper	1	\$ 300.00	\$ 300.00
9	Remove, Replace and Refit Rear Affected Area	1	\$ 300.00	\$ 300.00
10	Remove, Replace and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
11	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 710.00
Amount Before Excess				\$ 2,540.00
Add GST @ 7%				177.80
Total Amount Payable				\$ 2,717.80

Estimate prepared by: RAZALI

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: