3/2/22, 3:06 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21011991/UPA3Q2

02/03/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100423793 **Claimant Vehicle** SKW8969B Insured Vehicle No: SKK7835Z

No:

Date of Loss: 23/11/2021 Nature of Claim: TP Claim No: 7255391008SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW8969B

Make & Model: NISSAN KICKS PREMIUM PLUS, 1.2 L E-POWER (A) Engine No: HR12360023C

Reg. Date: 14/08/2020 (Man. Year: 2020) Chassis No: MNTFEAP15Z0000317

Colour: White Odometer: 23761 km

Engine Capacity: 1198 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17 Front Left Side: Rear Left Side: Bridgestone 7 mm Bridgestone 7 mm Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,025.70	1,783.08	1,242.62	41.07
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,660.00	1,380.00	1,280.00	48.12
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,685.70	3,163.08	2,522.62	44.37
	Approved Total (Overridden) (S\$)		2,500.00		
	(S\$)	5,685.70	2,500.00	3,185.70	56.03
	+ GST 7.00/7.00% (S\$)	398.00	175.00	223.00	56.03
	Nett Amount (S\$)	6,083.70	2,675.00	3,408.70	56.03
	+ Loss of Use (4.0 x S\$	660.00/day) (S\$)	240.00		
	+ Doc/S	Search Fee (S\$)	7.45		
	Ne	ett Liability (S\$)	2,922.45		
	Global Sum	Settlement (S\$)	2,900.00		

INSPECTION

Date of Assignment: 25/11/2021

Fastech Auto Pte Ltd (HQ)

Date Inspected: 25/11/2021 Inspected At: 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: **CHEW HSIAO TONG** NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER SPORT	Dented / Deformed	986.60 F	*850.00 FL
2	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	70.00 F	*- FL
3	1		*REAR BUMPER SPONGE	Deformed / Torn	81.40 F	*81.40 FL
4	1		*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
5	2		*REAR BUMPER REFLECTORS	Not Necessary	90.00 F	*- FL
6	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	220.00 F	*220.00 FL
7	1		*REAR END PANEL	Dented	441.10 F	*341.10 FL
8	1		*REAR END PANEL TOP GARNISH	Twisted	168.20 F	*168.20 FL
9	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	281.50 F	*281.50 FL
10	1		*TAILGATE	Not Necessary	647.90 F	*- FL
F=Fra	F=Franchise part. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 0.00/10.00% (S\$)			3,025.70 0.00	1,981.20 198.12	
				Total Parts (S\$)	3,025.70	1,783.08
			Report was unsubmitted dur	ing this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER TAILGATE MECHANISM	New	80.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	0.00
6	TO RESET & REPROGRAMME SYSTEM	New	150.00	0.00
7	TO SPRAY RUST PROOFING	New	80.00	30.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	900.00	600.00
9	TO PUTTY & SPRAY PAINTING	New	1,080.00	600.00
		Gross Labour Cost (S\$)	2,660.00	1,380.00
	Report was unsubm	itted during this print-out.		

< END OF ESTIMATES >