

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Not Authorised
Late
25/11/17
1/5 \$2500
4th day s.

VEHICLE No: SKW 8969B

NETT ITEM

1PC	REAR BUMPER SPORT	25/26	PSV	\$986.60	✓
2PCS	REAR BUMPER SIDE RETAINERS @ \$35.00	11		\$70.00	X
1PC	REAR BUMPER SPONGE	Be/Torn		\$81.40	✓
1SET	REAR BUMPER CLIPS	new		\$39.00	✓
2PCS	REAR BUMPER REFLECTORS @ \$45.00	11		\$90.00	X
1SET	REAR BUMPER REVERSE SENSOR	shoked		\$220.00	✓
1PC	REAR END PANEL	25	34:10	\$441.10	✓
1PC	REAR END PANEL TOP GARNISH	7ml		\$168.20	✓
1PC	REAR FLOOR PANEL TOOLS SPONGE	Torn		\$281.50	✓
1PC	TAILGATE	11		\$647.90	X
				\$3,025.70	

TO CHECK WIRING

TO DISMANTLE & REPLACED REVERSE SENSOR

TO TRANSFER TAILGATE MECHANISM

TO DISMANTLE & REFIX CUSHION UPHOLSTERY

TO DISMANTLE & REFIX REAR WINDSCREEN

TO RESET & REPROGRAMME SYSTEM

TOSPRAY RUST PROOFING

LABOUR FOR PANEL BEATING & REPLACED PARTS

TO PUTTY & SPRAY PAINTING

\$50.00	20
\$80.00	50
11 \$80.00	X
\$120.00	80
11 \$120.00	X
11 \$150.00	X
\$80.00	30
\$900.00	600
\$1,080.00	600
TOTAL	\$5,685.70

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-1981-2
10%
1783-08