

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 59976**  
Date Estimated : **09/11/2021**  
Prepared By : **Inthiran A/L Thurasamy**

**- ESTIMATE REPAIR FOR -**  
**BMW Asia Pte Ltd**  
**1 Harbour Front Avenue**  
**#15-02/07 Keppel Bay Tower**

**Singapore 098632**

**- ACCOUNT - 135**  
**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SNA9041B</b>	<b>WBA72AG070WX3548</b>	<b>22/07/2021</b>	<b>520i Sedan</b>	<b>2434</b>

DESCRIPTION	ORIGINAL PRICE	NETT
To replace rear bumper and attachments, bootlid, rear bumper carrier including knock out dented area caused by the accident.	1,700.00	1,700.00
To respray rear bumper and bootlid.	1,826.00	1,826.00
To check electrical wiring system and lighting at the rear section for proper function.	168.00	168.00
To remove old PDC assembly and reconnect to new bumper including conduct check for proper function.	168.00	168.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	504.00	504.00
To carry out body cavity preservation. (Per panel).	112.00	112.00
Sundries.	80.00	80.00

DESCRIPTION	UNIT PRICE	QTY	NETT
# EXPANDING NUT	2.85	2.00	5.70
TAILGATE ALUMINIUM	1,758.45	1.00	1,758.45
REAR BUMPER CARRIER	582.55	1.00	582.55
REAR BUMPER BOTTOM TRIM PANEL	309.95	1.00	309.95
REAR BUMPER BOTTOM REINFORCEMENT	86.30	1.00	86.30
REAR BUMPER TRIM PANEL (PDC/PMA)	1,627.25	1.00	1,627.25
REAR RH LIGHT TAILGATE LED	390.25	1.00	390.25

### # SUPPLEMENTARY ITEMS

Total Labour :	4,558.00
Total Parts :	4,760.45
Total Labour & Parts :	9,318.45
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,318.45
GST @7%:	652.29
Grand Total :	9,970.74

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Supplementary

Estimate No. : **b1 59976**  
Date Estimated : **09/11/2021**  
Prepared By : **Inthiran A/L Thurasamy**

**- ESTIMATE REPAIR FOR -**  
**BMW Asia Pte Ltd**  
**1 Harbour Front Avenue**  
**#15-02/07 Keppel Bay Tower**

**Singapore 098632**

**- ACCOUNT - 135**  
**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SNA9041B</b>	<b>WBA72AG070WX3548</b>	<b>22/07/2021</b>	<b>520i Sedan</b>	<b>2434</b>

DESCRIPTION	ORIGINAL PRICE	NETT
-------------	----------------	------

DESCRIPTION	UNIT PRICE	QTY	NETT
-------------	------------	-----	------

# EXPANDING NUT	2.85	2.00	5.70 <i>rec</i>
-----------------	------	------	-----------------

### # SUPPLEMENTARY ITEMS

Total Labour :	0.00
Total Parts :	5.70
Total Labour & Parts :	5.70